Tucson Fire Department Pioneer Hotel Fire Firefighter Individual Reports



CITY OF TUCSON



FIRE PREVENTION

FROM FF HECTOR M CORRALES

PIONEER HOTEL FIRE

DATE 15 OCT 7

I met Capt Carranta on the 4th or 5th floor, I assisted him in walking a man down to the mezzanine. Later on, I have no idea on which floor I was on, Fire Fighter Uthe and I broke into a room, we found an elderly woman laying behind the curtains, I put her on my sholder and took her down to the main floor. Another fire fighter took her, and started to give 1st Aid, she was still alive when I left.
Went up to the 9th or 10th floor, found Capt Sedlack, Engineers Cox and Tamayo giving 1st Aid to a woman, put her on max my sholders and took her downstairs.

HECTOR M CORRALES

Heeta M. Ponale

CITY OF TUCSON

7720

To Headquarters

FROM R. Danielson, L-3 "A"

SUBJECT Pioneer Hotel fire

DATE Oct. 15-1971

Ref: Memo #106

On Dec. 20-1971 I was the engineer on Ladder 3. Upon arriving at the scene I spotted the aerial on the Pennington street side. I then raised the aerial ladder to various windows and assisted in evacuating 7 people.

R. Danielson

E 1

CITY OF TUCSON

Headquarters FROM Firefighter C. H. Glen

SUBJECT Pioneer Hotel Fire

On December 20, 1970, I was a recruit in training. On Arriving at the scene, we recruits were sent into the building to assist in evacuating bodies. I helped carry four bodies down to the lobby.

720

CITY OF TUCSON

To Deputy Chiof K. F. Dirks	FROM Firefighter Fred L. Shipman
Sussect Pioneer Motel Fire	DATE_10-15-71

I was assigned to Ladder 3 and responded to the scane on the first alarm. Upon arrival we immediately put up the aerial and removed approximately 8 or 9 people to street level from the sixth and seventh floor. I then went in on the seventh floor and assisted 2 or 3 people to the smoke tower where they were taken down by other firefighters and proceeded up to other floors to clear rooms and assist bringing down 4 or 5 more persons.

Respectfully Submitted

Firefighter Fred L. Shipman

CITY OF TUCSON



To Headquarters

FROM Raul L. Romero

Subject Activities at Pieneer Hotel Fire, Removal of Victems DATE 10-17-71

As a member of the crew of ladder number one, on the night of the Pioneer Hotel Fire, I assisted in removal of live victems from the westside of the building on the aerial of ladder one. I also assisted in removal of one man from westside of building with a 45 foot extension ladder. The rest of my activities were centered on fire fighting activities.

Had I Lomero

200

AVOID VERBAL MESSAGES

CITY OF TUCSON

To Headquarters	John A. Engelkes	hn A. Engelkes	_
SUBJECT Pioneer Hotel Fire	DATE Oct.17,1971	DATE_O	_

While proceeding up the smoke tower on the Southwest side of the Pioneer Hotel a fireman asked me to help carry one(1) person down to the 2nd floor landing where another fireman took this person down the aerial ladder. This person was alive and talked to us while we were carrying him down. I helped carry him from approximately the fifth floor. This was the only person or victim that I helped at the Hotel.

cc: Staff 10

John A. Engelkes Sta# 10 'B' Shift 720

AVOID VERBAL MESSAGES

CITY OF TUCSON

TO HEADQUARTERS	FROM FIREFIGHTER E. L. DESCHAINES
SUBJECT PIONEER HOTEL FIRE	DATE OCT. 10 107

I ASSISTED IN MOVING APPROXMATELY FIVE (5) DECEASED VICTIMS BODIES FROM VARIOUS ROOMS AND FLOORS, ON THE WEST SIDE OF THE BUILDING, TO THE HOTEL LOBBY. FIRE FIGHTER KELLY ASSISTED IN HELPING ME MOVE A BODY FROM ONE OF THE ROOMS. THE REMAINING BODIES THAT I ASSISTED IN REMOVING, WERE IN THE HALLWAYS, WATING TO BE TRANSPORTED.

Emil Lamanda

RE.

CITY OF TUCSON

TO HEadquarters FROM Hobb	5
TO Headquarters FROM Hobb	DATE 10-12-71
I removed a body from about	t the 5th or
6th Floor. The time was about	
The man I believe was middle	
thought that he was dead.	



L. O. Hobbs

CITY OF TUCSON

TO HEADOVARTERS	FROM_	RAYMONI	D G	RIESMER	
SUBJECT EVACUATION OF BODIES AT PLOT	NEER	HOTELF	IRE	- 10-11-71	

AT THE PIONEER HOTEL FIRE OF DEC. 28, 1970, I ASSISTED ANOTHER FIREMAN IN EVACUATION OF ONE BODY, FEMALE, WHO APPARENTLY WAS AXPHYXIATED.

NO FIRE HAD ENTERED THIS ROOM, THE BODY WAS FOUND IN NORMAL SLEEPING POSITION IN BED. WE DRAPED THE BED SHEET AROUND BODY, PLACED BODY*IN SITTING POSITION ON A CHAIR. WE PICKED UP CHAIR, WITH BODY, AND CARRIED SAME FROM THE EIGHTH FLOOR TO FIRST FLOOR, WHERE AMBULANCE PERSONEL RETRIEVED BODY.

FROM OVERHEARD CONVERSATION FROM UNRNOWN SOURCE, I BELIEVE
THIS BODY WAS THE PRIVATE & PERSONAL NURSE OF AN ELDERLY GENTLE—
MAN WHO ALSO PERISHED IN THIS FIRE.

Raymond Friesmer Capt. Bravawan



CITY OF TUCSON

To Headquarters	FROM Firefighter Edward H. Bell	
SUBJECT Pioneer Hotel	Days 30 13 23	

At the Pioneer Hotel fire I assissted in removing a woman from the 9th.floor south side firestairs. We took her to the 2nd. floor where she was put into a stretcher and was removed to an ambulance. This woman was br-

breathing okay and was between 35-40 years old.

The 2nd person was a male between 50-60-years of age. I found him on the 9th. floor south east corridor in a room full of smoke. I took him out alone and led him down the south stairs to about the 5th. floor where two

other firemen led him out the rest of the way. His condition was excellent.

I later took a boy from two firemen who were coming down the south
stairs and carried him to the 2nd. floor and put him in a stretcher. I started close cardiac massage while a civilian administered mouth to mouth resucitation. We continued this until he was put into the ambulance.

The deposition of this victim is unknown to me. He was about 15-17 years

of age.

Firefighter

Edward H. Bell Sta. #11 "A" Shift

CITY OF TUCSON

To Fire Headquarters FRON Firefighter Hall Station #3 "A"

SUBJECT Pioneer Hotel Fire

DATE October 13, 1971

I assisted in the removal of one body ϕ an elderly lady) from the seventh or eighth floor to the ground floor where she was placed on a stretcher. I come across several people who were burnt beyond recognition but did not attempt to move them.

cc: Members personnel file at Sta #3

CITY OF TUCSON



James R. Burns, L-3 "A" Shift Headquarters DATE__10-15-71 SUBJECT Pioneer Hotel Fire

Ref: Memo #106

On Dec. 20, 1970, I was assigned to L-3. I assisted in raising a 45' ladder On the Stone Ave. side of the hotel, enabling several people to come down same.

I assisted in rescuing a woman from the 7th.or 8th. floor to the 3rd. floor. At that point we were relieved by two more men. Later on, I helped check rooms and helped bring down one body from the penthouse (11th.floor).

CITY OF TUCSON



To	Fire Hea	adquar	ters	 FROM.	 			
SUBJECT_	Pioneer	Hotel	Fire		DATE	Oct.	16,	1971

On the day following the pioneer hotel fire Iwas assigned to a detail which uncovered human remains (a foot & a knee). This was on the nineth floor, north west cornor of the building. Following orders from Fire Capt. A. Gregory, I reported these remains to an onduty Deputy Sheriff. The remains were not moved in my presence.

J.L.Bleess

Janus Loger

CITY OF TUCSON



To Headquarters, Fire Prevention Office FROM Firefighter J. D. Martin

SUBJECT Removal of victims at the Pioneer Hotel , Dec 20,1970 DATE Oct 16,1971

Upon arrival at the scene, Captain Berle, Salgado, and myself were instructed to relieve the Engine # 2 crew.We were told to assemble on the ninth floor to search for victims. Salgado and myself, along with ambulance attendants assisted in the removal of a charred victim to the lobby. The room was on the west side and we were told that other victims had been removed from the same area before our arrival. Capt. Berle and our crew then searched for other victims on the ninth floor and found none. I then was assigned to aid with the removal of firefighting equipment from the building

J. D. Martin

CITY OF TUCSON



To Fire Prevention

FROM F. E. Bruninge

SUBJECT Pioneer Hotel Fire

DATE 17 Oct. 1971

While operating the pump of E-2 I assisted eight to ten people over a ladder from the roof of Shoe City.

The names and any injuries of these people is unknown.

East, arnold R. Weine

CITY OF TUCSON



D. 10 12	
Subject Brief discription of part played in Bioneer Hotel firets 10/15/7	

Sir;

I was on Ladder #4 when dispatched to Pieneer fire.
Was with group of fireman that found one male caucasian apparently dead.

We placed body on a chair and carried to main floor where we turned over to fire and ambulance personel.

I was not and still am not sure of room number or time this action took place.

Marcus Cox

Markons Cox

×26

AVOID VERBAL MESSAGES

CITY OF TUCSON

To Headquarters	FROM Merle Diggins
SUBJECT Pioneer Hotel Fire	DATE Oct.17,1971

While under the Supervision of Capt. Hopkins; myself, Moreno, G., Hightower we transported one (Female) body from the 9th floor to the main lobby. This is the only victim that I helped move from one location to another while partic-pating at the Pioneer Hotel Fire.

Merle Diggins
Sta #10 'B' Shift

co; Sta# 10



CITY OF TUCSON

Headquarters

FROM Coons, R.E. Fire Fighter

SUBJECT Pioneer Hotel Fire

DATE 10 Oct 71

0139 hrs 20 Dec 70, Reported to Training Center. Then transported to Pioneer Hotel to aid in the removal of victoms from upper floors to Mezzanine.

Returned 22 Dec 70 to recheck building. In doing so found what appeared to be a foot of a woman or child.

Reported finding to a Training Captain.

MECEIVED Readquarters

25

CITY OF TUCSON

To H eadquerters FR	OM B Wells Sta 11 Ashift
Subject Pionoor Hotel	DATE 10 13-71

In the smoke tower on the South side of the building on approximately the seventh floor, I relieved a fireman carrying an elderly female corpse. Another fireman and myself carried her down the smoke tower to the lobby

where the ambulance attendace took over.

Later on the ningth floor, I removed a male corpse from a badly charred room. Another fireman and I layed him on a bed in an untouched room, (across the hall).

C. C. To Chief Rojeski
C. C. To Sta. 11

Bail & Welle Basil E Wells

CITY OF TUCSON

To_	Chief Dirks	FROM Firefighter C. Cook	
Grab i	Pioneer Hotel Fire	DATE Oct. 17, 1971	

While moving hose lines at the north stairway on the 6th floor, I was informed of a body in the east wing. I found a male body lying in the hallway in the vicinity of Room 627 and carried the burned body back to the north stairway landing.

C. COOK

CITY OF TUCSON

				y
C	Just	2	Y	X
		0	1	

	Headquarters	
(2)	mounday, for a	
Art and		

FROM Engineer, William Celaya

SUBJECT_ Ref. Master Memo # 106

DATE Oct. 17, 1971

In response to my activities, that involved removal of victims, I can only remember the name of one victim, which was Mrs. Steinfeld. I assisted in carrying Mrs. Steinfeld from one of the upper floors after I had met some fire-fighters in the stairway with the victim, and they needed help in carrying the victim. We carried the victim to the lobby area. I also assisted in the removal of other victims. The number and their names is unknown to me.

William Calaya Williams Celaya

CITY OF TUCSON

			7
	-		1.
7	6	Y	0
1	12	Xd	X

To_ Headquarters	FROM Clodfelter, R. L.	
SUBJECT Pioneer Hotel Fire	DATE 10-16-71	0

At the Pioneer Hotel Fire I was instructed to help remove bodies. I went to the 11 th floor and found two bodies in Room 1109. The bodies were on the floor by the foot of their beds. I and other firefighters wrapped them in bedspreads and carried them in chairs to the mezzanine.

I also helped carry one other body from the 11 th floor, down center stairs.

R. L. Cloffelter

CITY OF TUCSON

To Headquaters	FROM Purman Sta #S P
Susject Pioneer dotel Fire	DATE 10-10-71

I assisted in carrying a man from the sevents floor to the lobby. He was being carried in a chair. We was pronounced dead by a doctor in the lobby of the hotel. I do not know what room he was from as I releived someone else who had been carrying him.

Firefighter Furman Sta. # 8 B shift



ARA

AVOID VERBAL MESSAGES

CITY OF TUCSON

To_Headquarters	FROM Firefighter	Zielbauer Sta	. 14 "A
SUBJECT Pioneer Hotel Fire		DATE Oct.	13. 197:

I was in Training on the night of the fire. I was notified by phone At approximately 0120 hours and ordered to report to training. I reported to the Training Center at 0145 hours. From there I was transported to the fire scene where I was under the command of the Training Officers. I assisted in the location of bodies and their removal to the exterior of the hotel.

Firefighter James D. Zielbauer

Juroo D Jielbauer Captain Jack P. Simmons

Jack D. Limmon

CITY OF TUCSON

To Headquarters

FROM Firefighter D. L. Davis

Subject Pioneer Hotel fire

DATE Oct. 10, 1971

I helped carry six victims during and after the fire as follows:

- 1. A burned, unclothed, dead man from fourth floor hall down the south stairwell to the third floor where I was relieved.
- 2. A live woman down the south stairwell from the fifth floor to the third floor where I was relieved.
- 73. A dead man, from a room on the east side of the hall on about the sixth floor, to the lobby. (A dead woman was found in the same room.)
 - 4. & 5. Two charred, dead bodies, from a room on the west side of the hall on about the eight floor, to the mezzanine.
 - 6. A charred, dead body, from the same room, to the lobby. (About two or three more charred bodies were found in the adjoining room to the south.)

Sant Jani

Emil I Jamala, Capit

25



CITY OF TUCSON



To Chief Slagel (Fire Prevention) FROM Engineer Paul E. Cook

SUBJECT PIONEER HOTEL FIRE

DATE Oct. 17, 1971

I responed with Engine #3 as Engineer, on the 1 st alarm. We were at the scene at 0025. I noticed a large amount of smoke from the upper floors as we approached the scene from the south.

Engine #3 made a two line reverse lay from the South Dry Standpipe to engine #2. Engine #2 was at the hydrant about one-hundred yards east of Stone Ave. on Pennington.

As the rest of engine #3's crew had entered the building for rescue, I connected engine #3's lines to engine #2, and notified Engineer Brunning they were ready to be charged.

As I moved engine #3 to the curb, people in windows above were screaming that people were trapped on the north side of the hotel. I notice ladder #3 had set up on the South side of the hotel and ran to Captain Sedlack and informed him of the trapped people. We got a few more firemen and used ladder #1's forty-five foot extension ladder, as a car blocked the back of ladder #3. We raised the forty-five on the West side near the North end of the hotel. One to three victims came down the ladder from the four floor, I'm not sure as to how many came down.

There didn't seem to be any more victims that we could reach at this time. I noticed ladder #2 was lowering there aerial, so I went to assist as I throught they were going to put up the water tower. Instead they moved South of ladder #1, and raised their aerial for more rescue.

Captain Moran was looking for a 2½" to 1½" reducer, I told him I would check engine #3 for one. Engine #3 had been moved, and had made a two line reverse lay to the hydrant at Pennington and Scott. I ran to engine #3 and checked for the reducer, not finding one I asked Engineer Wells if he had one on engine #11. He got it and it was given to Captain Moran. Engineer Wells said he was not familier with engine #3 and that I should operate it as I was driving engine #3.

Engineer Wells said not to charged the lines until ordered to do so. As I was waiting for the command I noticed a large amount of fire on the East side of the hotel. Also I saw the lines being taken up to the East side of the hotel.

At 0130 I was told to charged the number one line, a short time later I was told to charged the second line. I pumped at 150 lbs. pressure until 0420, when I was told to shut down by Captain Shoup. Engine #3 pumped 45,000 gallons of water.

I then helped in picking up engine #3's hose and we returned to station #3.

Engineer Paul E. Cook

Paul C. Cook

AVOID VERBAL MESSAGES CITY OF TUCSON

Atal

To	Fire Headquarters	FROM	Richard P. Salgado	Sta.# 9-0
SUBJEC	Pioneer Hotel Fire Action	5	DATE_1	0/17/71

My activities at the Pioneer Hotel fire consisted of the following.

I was phoned at home by Capt. Berle to report to Sta. #1 on a full alert recall. At Sta.# 1 the crew of Eng.# 7 was assembled which consisted of Capt. Berle, Engineer Rankin, Firefighter J.D. Martin and myself. We were sent to the Pioneer Hotel and reported to the command post for further instructions. Chief Bayless instructed Capt. Berle to take his crew to the 9th floor to assist in anyway necessary. Upon reaching what appeared to be the 9th floor, we were directed to where five (5) charred victim's bodies were discovered. Firefighter Martin and myself assisted in carrying one of the charred bodies down to the lobby where we released it to the ambulance crews for disposition. I then returned to the 9th floor where I assisted in overhaul.

(signature)

XAL

AVOID VERBAL MESSAGES

CITY OF TUCSON

Headquarters

Fred K. Seal

SUBJECT Removal of People at the Pioneer Hotel fire.

10-9-71

My rescue activities were limited to the west side of the hotel

a little north of the main entrance.

First, I helped a family of four from a window on the seventh or eighth floor. This family consisted of a father and mother who were holding their two children, a boy and a girl, by one hand dangling down the side of the hotel. Next I helped two men from separate rooms about the fifth floor, I can't remember the exact floor.

After the above, I saw two ladies on the eighth floor. I helped one of them from the window to the ladder and passed her on to a fireman below me. The other lady collapsed in my arms as soon as I removed her from the window. I had to carry her to the ground. This was all I helped remove from the hotel via the Aerial Ladder.

After firefighting activities by the ladder pipe were concluded and carrying supplies to firefighters on the upper stories, I made my way to the suite belonging to the Steinfelds. Other firemen were there at the time and shortly after I got to this suite, I helped place them in chairs and carry them down the area on the mezanine where doctors were examining

This, to the best of my knowledge is the extent of my rescue activities at the Pioneer Hotel fire.

And K. Sur



CITY OF TUCSON

To Headquarters	FROM D. E. Vanover
SUBJECT Body Removal (Pioneer Hotel)	DATE 10/10/71

I was involved in the removal of seven bodies from upper floors of the hotel. Two of them were on the third floor in a relay take over from other men who had carried them from higher stories. The next five were from one two bed room apt. on one of the upper floors possibly the seventh or eighthiit was on the stone avenue side with windows facing west. I was assisted in removing these last bodies by firefighter D. Davis and two men from Kords ambulance service. Due to the burned condition I did not try to obtain their ages or sex we placed them in rubber sacks or sheets from the unburned portions of the hotel. two of these victims were taken to the lobby by usawe were reclieved by other personnel on the mezzanine floor of the other three vitims.

David E. Vanover

Eml I Jamonda, Capt



CITY OF TUCSON

То	Headquarters		FROM_	R.C.Baldwin	
SUBJECT	Pieneer Hotel	Fire			DATE 10-10-71

In compliance with master meno 106 of 6 Oct. 1971, I was involved with the removing of one body at the Pioneer Hotel Fire. The location was on one of the upper stories at the south-west corner of the building. There were two victims in this room, one male victim and one female. Due to the appearance of the room the male victim was an invalid. The female victim appeared to be a nurse. Other firemen and my self placed the male victim on a chair, covered him with a sheet andt tied him in the chair with a sashcord from one of the windows. We then carried him to the mezzanine floor where four other people took him from us. This is the only victim I had any activity with even though I saw other victims at other times and locations during the fire. Because of the time laps between the fire and your request this is about all I can remember of this incident.

R.C. Baldwin Fire Engineer

Capt. R. W. Oppel

P. C. Rablem



AVOID VERBAL MESSAGES CITY OF TUCSON

To Headquarters			FROM Firefighter G.A. Moreno			eno			
Supu	Pion	eer	Hetel	Fire			DATE	10-10-71	

I assisted in the removal of three dead bedies from the tenth floor. Two of the bodies were in room 1020, one was a nurse and the other was an elderly man. The other victim was in the middle of the hall.

There was another body in the same room, but I didn't help in removing it. All of the above victims were removed to the mezzanine floor where an ambulance crew took them.

Firefighter G.A. Mereno

R. W. O.



AND

AVOID VERBAL MESSAGES

CITY OF TUCSON



To Headonarters FROM I. D. Wise DATE 10/18/71

SUBJECT Pioneer Hotel Fire DATE 10/15//1

I arrived at the scene driving Rescue 1 and immediately put my turn-outs on and took the E&J resuscitator and first aid kit to the main entrance of the hotel. At this time I heard someone scream which caused me to look up. A girl had jumped from a room from an upper floor. She came down to the mezzanine where she straddled the balony and then fell to the sidewalk about 10 feet from me. Iwent over to her and tried to get a pulse but failed to find one.

I then helped set up the areial on Ladder 1, and helped to removed victims. First was a family of four, second was two lelderly women of which one had to be carried all the way down, third was a man in a room all alone, fourth was a man and his wife, and fifth was an elderly woman who was in a room all alone. These are all the victims I can remember taking down the areial.

I then went to the seventh floor with Captain Carranza where we were told that there might be two juveniles in room 712. We entered the room and found one boy laying in the southwest corner under the window and the other was in the bathroom laying up against the door.

I believe these were all the people that I helped remove from the hotel as near as I can remember.





CITY OF TUCSON

		-1,		
5	_ <	A	Tol .	
	/	10	P. /	. 7

To Headquarters	FROM	Charles	E.	Highhouse	Stat 9	2(c).
Suggest My activity at the Pienes	r Hotel fi	re		DATE	10-16-197	71

I was called in because of the full alert and was assigned to unit 2523. Unit 2523 was dispached at approximatly 01:30 A.M. Upon arrival we reported to the command post and were told to assist at the 8th floor. We entered the building through the smoke tower. Upon reaching the 6th floor I assisted in carrying a teenage male to the 2nd floor. We administered mouth to mouth resuscitation to the youth all the, but there was no response. I Then went to the 8th (way)

floor where I assisted in carrying a female victim to the mezzanine. I then went to the 10th floor with a medical team in search of victims. We came upon apartment 1018 where we found two victims, an elderly male and his nurse. Both were pronounced dead in the room by the doctor. I assisted in carrying them to the 2nd floor lobby. Directly after this we returned to station 10# where we were released.

Charles E. Blighboure

CITY OF TUCSON



То	Headquarters,	Fire Prevention	FROM	Engineer	Guy	Rentfro			_
SUBJEC	. Pioneer Ho	tel Fire				DATE Oct	17,	1971	

When I arrived at station #3 at 0130 hrs. I was assigned to Reserve Engine #8027. The crew was Capt. Mazon, Eng. Lujan, Cammarano, Rentfro, Palko, and firefighter \$\vec{g}\$. Davis. We were dispatched to the scene and sent to the 9th and 10th floors to aid the search for victims.

Myself and three other firefighters removed a male deceased victim from the bed in room #1003 and placed into a chair. We carried him to the foot of the stairway in the lobby. The other victim, a deceased male, was enroute on the stairway from either the 9th or 10th floor when I assisted three other firemen carry him to the lobby. A Doctor met us at the foot of the stairway in the lobby and pronounced both victims dead. Both appeared to be the victims of carbon-monoxide poisioning. We placed them on an ambulance cot and returned to the upper floors to continue the search.

Capt. Mazon and most of his crew, encluding myself, were returned to station #3. I was relieved of duty at 0800 hrs. Dec. 21st.

Engineer L-2 Sta. 7 "B"

CITY OF TUCSON

7	dal	
1	761	
	1	del

То	Headquarter	s, Fir	re Prevention		FROM	Firefighter	D.	E.	Kelly
SUBJEC	Pioneer I	Hotel E	ire	Master	Memo	106		DATE	17 Oct 1971

At approximatly 0135 myself and six other Recruits arrived at the scene with Fire Capts. Gregory, Frana, and Cirivello. We were disptchated by the Fire Commander to the upper floors to make a room to room search for victims. On the tenth floor in room 1009, myself and three other firefighters carried a female victim to the lobby. She was apparently a victim of carbon monoxide poisiong. I also assisted in carring three other victims from the ninth and tenth floors to the lobby. After making several more room to room searches of the hotel, I, then assisted in removing firefighting equipment from the building. I then remained on fire watch on the sixth floor untill 0830.

Three days after the fire I was assigned to a special detail to make a room to room search for a Handi-Talki- radio. Myself and another recruit found what appeared to be a foot and a knee joint. These parts were found in room 906. These body parts were put in a sheet and left in the room. A Police officer on watch on this floor evidently directed ambulance personnel to the parts.

D. E. Kelly

Firefighter, Station 7

uBu

AVOID VERBAL MESSAGES

CITY OF TUCSON



To Headquarters

FROM F. A. Tamayo

Subject Pioneer Hotel Fire

10/15/71

On the night of the Pioneer Hotel fire I was tillerman on L-03. On arrival at the scene we put our aerial ladder into operation on the Pennington Street side of the hotel. I assisted an old man off the 8th floor. I helped the man down the aerial and then we moved the ladder over to the east and down about one floor. I went back up the ladder and carried a little girl down with her mother and father following us. We moved the ladder to another window where there werethree women. I went uppand assisted them in getting started down the ladder. Captain Sedlack went up the ladder to help the three women down and I went into the room where the women had been. From that room I went into the hall way which was about the middle of the east wing on the 6th floor. There I met Captain Jones who informed me that he had come up the fire escape on the north side of the wing on the 6th floor, in search of an old woman which had been seen from the outside. We found the lady and I led her to the fire escape on the north side of the annex. Later on I met Captain Sedlack, Mark Cox, Hector Corrales and a couple other firemen in a room on the 9th floor on the southwest corner of the hotel. In this room we found an unconscious woman and after administering oxygen she was carried down by Hector Corrales.

Frank A. Tamayo

Frank a Tamayo

	To a Salary	W WW		
4 4 3		12-28-70		
Name	Dr. or Hospital	Status	Injury .	Time Los
/Gus A. Moreno	Dr. Frankel	Checked and sent	Sprained right ankle	still of
Reynold Strand	V.A. Hospital		Smoke Inhalation	1 day
Chester Adams	Dr. Malib	Stayed overpisht in Checked at Homeital	Strained back	still
Name and America	St. Mary's Hospita	Checked at Hospital and released		230
Frank A. Tamayo	Dr. H. W. Kohl	Checked at Hospital	Smoke Inhalation	none
Dale A. Konigsfeld	None	0. K.	Smoke Inhalation	none
Roland H. Banton	None	O*K	Smoke Inhalation	none
Pedro Trujillo	St. Mary's Hospital	Admitted to Hospita	l Broken Pelvis	still of
George Stedman	Carl "ayden"	Checked and released	Strained Back	off 10
Larry A. Cunningham	Dr. Bacus	Checked and released	Strained back muscle	none
Arthur Apodaca	St. Mary's Hosp.	Admitted to hospital	Broken Ankle	still
Leonard Hobbs	Carl Hayden	Checked and released	Back Strain	still
Marcus Cox	St. Mary's Hospital	1 Checked and released	Hip and leg & Smoke Inhalation	none
-Ellis Cook	Carl Hayden	Checked and released		2000
	1.	(In hospital overni	ght) shoudder	none
Jack Harris	Command Physician	Admitted to Hospital	Smoke Inhalation Blisters on hands and	
Radolfo Lopez	Command Physician at scene	Checked and released	Smoke Inhalation	none
Fred Sprung	TMC	Admitted to Hospital	Smoke Inhelation	off
H. M. Adams	None	O.K.	Strained right should	er none
Carl T. Cook	None	O.K.	Bruised Toeparight on right foot	none
H. Wray	None	0.K.	Shoke Inhalation	none
W. P. DuPont	None	C.K.	Smoke Inhalation	none
/A. J. Caranza	DR. MAKT. N	wette 7	Smoke Inhalation ?	2 DAY
Charles Hammel	None	- O.K.	Smoke Inhalation	none
, R. L. Delahanty	None	O.K.	Smoke Inhalation	none
	1-12-1			
G. J. Jacome	None	0.K.	Smoke Inhalation	none
Fred Scal	None	C.K.	Smoke Inhalation	none
R. W. Jones	None	0.K.	Smoke Inhalation	none
W. S. Foster	None	O.K.	Smoke Inhalation	none
√ Raul A. Romero	None	0.K.	Smoke Inhalation	none
V Lury D. Wine	None	0.8.	Smoke Inhalation	none
Alvin H. Gregory	None	O.K.	Strained lower back	none
J Ellis Franklin	TMC	Admitted (kept overnight)	Cacerations and stra	n still
· E.H. GELL	Baker and Edwards		to arms, shoulderes, &	off 3
W D. H. WILL	-			



HELP US PREVENT FIRE

FIRE DEPARTMENT

CITY OF TUCSON

TUCSON, ARIZONA 85726 FIRE PREVENTION DIVISION 602 791-4502

E. Dean Holland Fire Chief



Re: Pioneer Hotel Report

December 5, 1977

Heidi Sanders Rt. 1, Box 482A Casa Grande, Arizona 85222

Dear Heidi.

Thank you for sending us a copy of your report. It reads very well and pulls the reader along. You know from the first paragraph that the Fords got out, but you find yourself urged along by the suspense—how did they get out? We hope the instructor finds it so as well; and we are happy that we were able to assist you with the facts that you required.

Sincerely yours,

R. B. Slagel, Chief

Fire Prevention Division

RBS/LDG:LSM:1sm

L. D. Gilmore, Captain

Fire/Arson Investigation Unit

11 20.77

Dear Mr. Stagel and Capt. Gilmore, Thankyow so much yor taking the time to help me with this story. although the main theme of the story deals with the Ford interview, everything they mentioned had to be backed by fact. That is where you really helped out. I hope you enjoy the story, morning. Surely let you know. Mope both of your families have a nice Thanks giving -Thanks again, Ideidi Sanders Neidi Senders NGO 310/Itule In-Depth 11-21-77

Pioneer Hotel

Dr. William Ford, a Casa Grande physician, sat at the round poker table in his family room. He was wearing a faded green scrub suit, ready to make the evening rounds at Hoemako Hospital.

His wife, Regis, sat next to him. Together they recalled the night they shared at the Pioneer Hotel in Tucson on Dec. 20, seven years ago when the landmark hotel was set aflame.

Twenty-nine persons died and 34 were injured in the fire.

The Fords escaped although Mrs. Ford was hospitalized overnight.

FIRST ADD/senders/Pioneer Hotel

"We rarely ever talk about it," Ford said. "We are just so grateful to be alive."

The Fords had reservations at the hotel for Dec. 19 and checked into their room in time to change clothes before attending a wedding that evening. Since Mrs. Ford had not been feeling well all day, they did not attend the reception.

when the Fords returned to their room after the wedding, Ford gave his wife some medication for her upset stomach, which also put her to sleep. About midnight Ford awake to the sound of screams.

whhat woke me up was the noise. We had left our window open and I could hear the yelling and hollering. Then, when I was up, I could smell the smoke," Ford said.

The Pioneer Hotel had three elevations. The main structure was 11 stories with a roof garden. A six-story east wing was attached to the main building. A two-story level with the swimming pool area covered the rest of the rear area of the hotel. SECOND ADD/Sanders/Pioneer Hotel

The 29 persons who died all occupied the sixth through eleventh floors. The Fords occupied an eighth floor room overlooking the pool.

After realizing the hotel was on fire, Ford tried to arouse his wife. He had trouble waking her because of the medication and eventually pushed her out of bed with both feet.

Ford had remembered seeing the fire escape at the end of the hall next to the elevator. They decided to run. "The first thing we did was go into the bathroom and get wet towels to put around our heads," Mrs. Ford said.

"We made an agreement that we would hold hands," Ford said. "I would open the door quickly and we would run. If it was too bad out there we agreed to come back in the room."

They had decided to count steps so they would be able to find their way back if necessary. It only took three steps to know they could go no farther.

THIRD ADD/Sanders/Pioneer Hotel

"You could see the color of the fire above the rolling black smoke. It was rolling like a tornado."

They immediately returned to their room and ran for the window.

with their door open for that short while, the Ford's room
had filled with smoke. "We stood on the windowsill holding
onto the frame and hung our heads out the window to breathe,"
Ford swid. The windows were the old fashioned roll-out kind
with a setal frame.

The fire was set on two locations on the fourth floor by an arsonist. According to the Tucson Fire Department fire report, "With devastating speed, the fire spread and turned into a holocaust never before experienced by the city of Tucson. The open stairways, synthetic carpeting on the floors, vinyl wall covering, and combustible contents caused the fire to extend up the open stairways and engulf the hallways of the fourth through eleventh floors with inconceivable speed."

FOURTH ABB/Sanders/Pioneer Hotel

Louis C. Taylor, 17 at the time of the fire, was convicted on July S, 1975, of 28 murder charges. He is now serving 28 life sentences in the Arizona State Prison. One person died a year after the fire and although the death was caused by the fire, Taylor was not charged in that death.

A family of five, staying in the room next to the Fords, died in the fire. As the Fords hung to their window they tried to help a young boy in the family.

The little fellow next to us had gotten panicky. We tried to talk to him to calm him down a little bit. He would keep coming to the window and then going back into the room.

Smoke was billowing out over his head because someone had left their hall door open.

"Then, when he was hanging to the window he either jumped or fell. We could hear him hit the roof below us and thought he was dead, but he survived the fall. Apparently he was just unconscious. The rest of the family had already been burned or asphyxiated in the room," the Fords said.

FIFTH ADD/Senders/Pioneer Hotel

The boy eventually died. Four other members of his femily who were in the room that night also died. Two of them died after falling. The others died from burns.

The Fords hung to their window thinking they'ld be safe for a little while. Finally N there was a momentary sound of relief.

"We could hear the sirens. It sounded like just everything was coming and then there was no sound at all. We one came to the back to help us for a long time," Mrs. Ford said.

The fire reached the fourth alarm level. The first company arrived at the scene approximately three minutes after receiving the call. It involved 75 percent of all the equipment Tucson had available.

The trucks could not fit in the alley behind the hotel.
When the firemen finally got to the back of the building, the
Fords had started their descent.

The Fords could see people jumping, and falling and being burned up while they watched from their window. They made the decision that they, too, would try to find a way down.

SIXTH ADD/Sanders/Pioneer Hotel

"We both knew that we were dead, we had settled that.

There was just no way that a we were going to get out. The different windows around us were lighting up and people were jumping and still there were no firemen down there." the Fords said.

The fire investigators believe the fire was ignited around midnight. It spread swiftly but was not reported to the fire department until 12:19 a.m. by a cashier at the Downtown Shoppers Garage, one block south of the hotel.

Ford said, "We were hanging out the window and had said goodbye to our children and to each other and we were holding hands." (Six of the Form's mine children had planned to make the trip with their parents and changed plans at the last minute.)

It wasn't until this hopeless moment that Ford spotted
a four inch cost iron pipe running down the side of the building on the other side of the crenked-out window.

SEVENTH ADD/Senders/Pioneer Hotel

He reached around the window and shook the pipe to be sure it would hold. Then he took a chance and leapt around the window, grabbed the pipe, and started his descent.

"I could get a good grip of the pipe with my hands and

feet si I started down and yelled for Regis to come on. But,

as soon as I got below our window, the nice easy cast iron pipe

changed to a smooth metal conduit pipe that had been belted

onto the wall. I could hardly get a grip with my hands,"

d

Porm said. Mrs. Ford did not follow.

With his toes and fingers, Ford got enough grip to work his way down. Between floors he was able to pull the pipe away from the wall a little bit which made it easier.

"I remember saying to myself that Regis will never be able to do this," Ford said.

As Ford made his way down he spotted Dr. Lewis Beck, an internationally known philosopher who was in Tueson for a moeting at the University of Arizona. He was about to jump from his sixth floor window when Ford called out to him and showed him the pipe. Beck then followed Ford down the pipe to the second story roof and safety.

EIGHTH ADD/Senders/Pioneer Hotel

"When I got down to the floor I just couldn't believe it.

There were still no firemen

THEREXYSKIII WEEKEN THERE there so I ren across the sub-roof

and just got to the edge and there was a two or three foot

parapet that came up with tile on the top of it," Ford said.

"I started over that and I could see a fireman. I started screaming "My wife! We need help! We need help!"."

The firemen came carrying a ladder that only reached to the fourth floor. Another group followed in with an extension ladder. Ford tried to help them put it up.

"They said they didn't need me so I went in the corner and started to pray. I could see the ladder going up. I looked up and I could see my wife in the window with the fire behind her and she lit up like a sinlowatte." Ford said.

Two firemen were injured while trying to reach Mrs. Ford.

One firemen fell off the ledder. The extension of the ledder collepsed catching the ankle of the other man and leaving him dangling upside down.

NINTH ADD/Sonders/Pioneer Hotel

Wrs. Ford had tried to reach the pipe to follow her husband down but couldn't small reach it. She spood in the window hoping help would come when the doon connecting the Ford's room with the family's next doon exploded with fire.

There was a firemen with a group of teen-agers in the six-story roof near the Ford's window. They tried to throw Mrs. Ford a rope and urged her not to jump.

"After the explosion the frame on the window was getting red hot and I couldn't stay there. I had to go somewhere," said Mrs. Ford. "I really didn't think I was going to make it. I was really scared."

Mrs. Ford jumped around the pipe and started her way down.

The kids finally got the rope over to her and she tied it

around her waist while gripping the pipe.

"I no more got that rope on and I fell. My toe caught in the pipe and I was hanging upside down," Mrs. Ford said.

"I pulled back up using the rope and then used it to inch down the pipe again." THIR ADD/Sanders/Pioneer Hotel

The whole time that this was going on, the firemen had set the extension ladder up to the sixth floor. Mrs. Ford went down the rest of the way by ladder.

The Pioneer Hotel met the minimum standards for safety

e sat by the city for its age and class, said L.D. Gilmore,

captain of the arson unit. Although new buildings were putting

in automatic aprinkler systems and closed staircases, it was

not a requirement for the older buildings.

The fire initiated immediate change of standards requiring these two prevention measures for non-residential multiple story buildings in Tucson.

The open staircase at the Pioneer worked like a chimmey, shooting the fire up, said Gilmore said. If the staircase had been closed, the fire probably would have been contained on the fourth floor.


After repairs, the hotel was reopened, but failed. It is now being used as an office building. SLEVSNYH ADD/Sanders/Pioneer Hotel

The Fords returned to the hotel the day after the fire to see their room. Hrs. Ford was able to retrieve a watch that was sentimental to her.

"Now when we stay away from home, we always get a room on the first floor," said Mrs. Ford. "Sometimes we have to drive extra miles to get one."

440

Chypetram TUCSON FIRE DEPARTMENT FIRE REPORT PIONEER INTERNATIONAL HOTEL 80 No. STONE AVE. DECEMBER 20, 1970



HOTEL BACKGROUND

The Pioneer International Hotel is located in the heart of downtown Tucson at the intersection of North Stone Avenue and Pennington Street. This attractive hotel building was constructed in 1929 by one of Tucson's most prominent business men, Mr. Harold Steinfeld. The hotel was a popular place for tourists, dignitaries, and celebrities to stay when visiting Tucson. The Cleveland Indians made the hotel their home while conducting their annual spring training program in the Old Pueblo. Vice President Agnew recently occupied a seventh floor suite during a short visit for a speaking engagement in the hotel's attractive ballroom. The warm hospitality extended to our neighbors south of the border gained fame for the hotel, and soon many of the prominent families from the State of Sonora, Mexico, made it a point to stay at the Pioneer Hotel while on business and pleasure trips in the City. Local and out of town groups enjoyed holding their banquets, dances and conventions in the main ballroom of the hotel. In the past 41 years of existence, the Pioneer Hotel loomed as one of Tucson's most prominent landmarks.

CONSTRUCTION

The Pioneer Hotel has three distinct elevations. The main structure is 11 stories high. The dimensions are approximately 128 feet by 56 feet. It has a roof garden with exterior walls that make it appear to be a 12-story structure. The east wing attached to the main structure is six stories high and the dimensions are approximately 54 feet by 71 feet. There is approximately 15,000 square feet of structure that is two stories high to the north and east sides of the main structure and east wing. The area of each floor from the third floor through the sixth floor is approximately 11,000 square feet. The area of each floor from the seventh floor through the 11th floor is approximately 7,000 square feet. There is a full basement under the building. The exterior walls are constructed of reinforced poured concrete. All columns, tees, beams, and ceiling joists are constructed of reinforced poured concrete. Partitions are constructed of hollow three-inch tile with one-half inch of plaster on both sides. All the floors are also constructed of reinforced poured concrete. The roof of the two-story section on the north side has a roof made of metal decking with insulation and built up composition. The two-story section on the east has wooden decking with built up composition roof. The remainder of the roofs are constructed of reinforced poured concrete.

All public hallways had noncombustible fiberglass accoustical tile ceilings hung on steel supports. The space between this ceiling and the floor above concealed the air conditioning plenums, electrical conduit, and water lines. Doors off the hallways were unrated wooden panel with wooden door frames. The public hallways were lighted by fluorescent light fixtures, each having a plastic defuser held in place by a wooden frame. The floors in the hallways and 22 inches of the walls above the floor were covered with a good grade of synthetic carpeting. At the 22 inch level there was a 3/4 inch by 8 inch plywood board with a laminated plastic surface paralleling the floor. The remainder of the walls were covered with a vinyl wall covering.

The hotel has two interior stairways and one smoke tower. One open stairway leads from the main floor lobby to the second floor mezzanine. There are self closing, fire rated doors on the second floor leading to an open stairway, which extends to the sixth floor and terminates in the east/west public hallway approximately 12 feet east of the elevator lobby. The other open stairway is in the north/south public hallway approximately 40 feet from the north end and goes up through the 11th floor to the roof. At the roof

level, there is one solid door leading to the roof and one louvered door leading to an equipment room. In the center of the hotel there is a narrow, open stairway leading from the basement to the second floor office area. At the south end of the 11th story tower there is a smoke tower which leads from the second floor mezzanine to the roof. There are two exterior fire escapes. One is located at the north end of the 11th story tower. The other is located on the north side of the east wing and is accessible only through a guest room.

The hotel building has a total of four elevators. There are two manually operated passenger elevators which go from the basement to the 11th floor. They are located at the south end of the north/south public hallway. There is one manually operated service elevator, which runs from the basement to the 11th floor. It is located approximately 20 feet east of the north stairway. There is an open freight elevator in the northeast corner of the two-story section which goes from the basement to the second floor kitchen.

OCCUPANCY

The street floor of the building consists of the main lobby, dining room, cocktail lounge, and several businesses. On the second floor there are several banquet rooms, a kitchen, business offices, and a large ballroom. The third floor through the 11th floor consists of approximately 175 hotel rooms and suites. At the time of the fire there was a total of 113 permanent and overnight guests staying in the hotel. Several of these guests were visitors from Mexico. Approximately 350 persons were attending a Christmas party in the large ballroom on the second floor. Some members of the hotel staff were on duty.

FIRE LOAD

Most of the hotel rooms and suites had typical furnishings, such as wooden dressers and chests, beds, drapes, etc. The only furnishings in the hallways consisted of one wooden table 24 by 48 inches and two wooden chairs. These were located near the elevator on each floor. The floors of hallways and rooms were covered with a good grade of synthetic carpeting. The vinyl wall covering, painted wooden door frames and painted doors also contributed to the fire load.

FIRE PROTECTION

The building has a wet standpipe system with the Fire Department connection on the Stone Avenue side of the building. There are two hose cabinets on each floor up through the sixth floor and one cabinet on each floor from the seventh through the llth floor, which are connected to the wet system.

There is also a dry standpipe with Fire Department connections on the Pennington Street side of the building. This system consists of one standpipe, which goes up the smoke tower with one 2-1/2 inch outlet at each floor.

The building does not have a sprinkler system. The stairways in the hotel are open and unprotected. There are no heat or smoke detectors in the building.

WEATHER

The United States Weather Bureau at the Tucson International Airport recorded a temperature of 43° Fahrenheit, relative humidity 69, wind 9 knots from the southeast and a clear sky at 2300 hours on December 19, 1970.

STORY OF THE FIRE

Fire investigators believe the fire was ignited around midnight by

an arsonist in at least two separate locations on the fourth floor. The fire went unnoticed for several minutes. Then, with devastating speed, the fire spread and turned into a holocaust never before experienced by the City of Tucson. The open stairways, snythetic carpeting on the floors, vinyl wall covering, and combustible contents caused the fire to extend up the open stairways and engulf the hallways of the fourth through the 11th floors with inconceivable speed.

The fire gutted one room on the sixth floor, three rooms on the eighth floor and two rooms on the ninth floor. Searing heat and acrid smoke engulfed the hotel from the fourth through the 11th floors, causing a large loss of life in the upper floors.

REPORT OF THE FIRE

Incoming alarms, dispatches, and radio communications are recorded on tape. The time is recorded every six seconds on the tape. Times indicated on this report were taken from these tapes and are reasonably accurate.

The first report was received by the Fire Dispatchers at 0019:15 hours on December 20, 1970, reporting a car fire outside the Pioneer Hotel. This was reported by the cashier at the Downtown Shoppers Garage, 90 North Church Avenue, one block west of the hotel. Additional information was not given by the cashier, as he stated he could not leave the cashier cage unattended.

The second report was received from Emory Forkin, calling from the Tucson Federal Building one-half block south of the hotel, reporting a fire on the seventh floor of the Pioneer Hotel. This report was received at 0019:33 hours.

A third report of the fire came from the Pioneer Hotel staff at 0019:45 hours, stating that there was fire on the third floor and smoke in the upper floors.

The Fire Department continued to receive reports of the fire. At 0022:31 hours a person at the Old Pueblo Club in the Tucson Federal Building reported the Pioneer Hotel on fire. The person broke off the report by stating, "Oh, here they come. Well, I see the fire trucks now."

Of the many reports received by the Fire Department, the locations reported varied from the second floor to the seventh floor. Early reports indicated that people were yelling for help and breaking glass windows.

FIRE DEPARTMENT BACKGROUND

The Tucson Fire Department provides fire protection within the city limits of the City of Tucson, which covers approximately 80.9 square miles and has a population of 263,000 people. On December 20, 1970, the Fire Department had a total compliment of 288 firefighting personnel. The Fire Suppression Division normally has 79 firefighting personnel and three chief officers on duty. There are 12 fire stations, housing 13 engine companies, 4 ladder companies and 5 rescue companies. The department has 6 apparatus in reserve that can be manned by offduty personnel and put in service as engine companies when needed. Most of these reserve apparatus are overage for active service.

SUMMARY OF FIRE DEPARTMENT OPERATIONS

A total of four alarms were dispatched to the hotel fire, consisting of 11 engine companies, 4 ladder companies, (1 ladder company was operating with a reserve engine) and 5 rescue companies. A total of 70 on duty firefighting personnel manned these companies. Three on duty chief officers also responded.

Fire companies from the first alarm arrived at the scene approximately three minutes after the first report was answered by the Fire Dis-

patchers at the Communications Center.

The first arriving companies and chief officers reported considerable smoke coming from windows of the upper floors of the hotel. People were in a state of panic and yelling for help. Some of them were hanging from windows, standing on ledges and balconies waiting to be rescued. A woman jumped to her death near the first arriving ladder truck as the aerial was being extended. Three other persons died from falls during the fire. As the first companies entered the hotel, it was obvious that the building was well involved with fire.

The Fire Commander, Assistant Chief Richard Bayless, established a command post on the southwest corner of Pennington Street and Stone Avenue. A combined operation of firefighting and rescue became the first major objective of the Fire Department. The two on duty District Chiefs divided the command for interior firefighting operations.

Ladder companies immediately spotted their trucks and extended their aerials for rescue operations. Several of their hand ladders were also used for rescue. All of those persons in need of rescue who came into view of the ladder companies were successfully rescued from windows, balconies and ledges. After Ladder 1 completed their rescue operations from the exterior of the building, they used their ladder pipe to fight fire through the windows on the eighth and ninth floors.

Engine companies assigned to firefighting took hose lines to each of the fire floors and attached them to the dry standpipe connection. These lines and the wet standpipe system were used to fight most of the fire in the hallways and rooms. Two lines were laid to the rear of the building and some firefighting was done with these lines after being taken up ladders.

The Chief of the Fire Department, L. F. Peterson, responded from his home, and arrived at the scene a few minutes after the first arriving companies. He initiated a "Yellow Alert", which is a crisis requiring the assistance of outside agencies or other city departments. At this time he assumed the position of Disaster Operations Chief, responsible for coordinating the activities of all agencies or departments at the scene. The primary need at this time was for transportation and medical treatment of victims.

As off duty chief officers arrived at the scene, they were assigned sectors (areas of responsibility) for firefighting, rescue, staging areas, etc. Off duty firefighting personnel were organized into companies at Station #1 and then sent to the scene to carry out a specific assignment, bolster company strength of companies at the scene, or to relieve injured or fatigued personnel. Ninety-two off duty firefighting personnel reported to the scene during the emergency.

A Fire Department Operations Center was established at Station #1 four blocks from the fire scene. At the Fire Department Operations Center several off duty chief officers reported and coordinated the support of manpower and equipment needed at the scene. They also arranged to provide fire protection for the rest of the city during the emergency. This was accomplished by calling in five mutual aid fire companies, manning four reserve engine companies with off duty men and utilizing the two on duty companies that did not respond to the scene. All of these companies were assigned areas left vacant by companies at the hotel fire.

Approximately one hour after the initial dispatch, the fire was under control. The objective of the Fire Department now was to make a systematic search of every room for victims and to extinguish any existing smoldering or spot fires. To establish a control of rooms checked, a white rag was tied to the door knob of each room after it was thoroughly searched and cleared of any victims. This operation lasted for approximately two and one-half

hours, and at this time some of the companies cleared the scene and returned to the station. Several companies remained to check for smoldering fires and to gather equipment scattered throughout the hotel. By 0800 hours all excepting one company had cleared the fire scene. This company maintained a fire watch until 1450 hours on December 20, 1970.

At this time the hotel was turned over to the Fire Prevention Division to conduct an investigation to determine the cause and place of origin of the fire. Their on-the-scene investigation continued until 1900 hours on December 31, 1970, at which time the hotel was turned over to the management.

R. B. Slagel, Chief of the Fire Prevention Division, after completing the on-scene investigation of the fire stated in his report that "the fire originated on the fourth floor in the public hallway and there were at least two major fire origin areas separated by approximately 60 feet. No natural or accidental causes could be found. In my opinion, this was a deliberate, man-made fire, with malicious intent; therefore, the fire cause is arson".

ACTIVITIES OF OTHER AGENCIES

POLICE DEPARTMENT

The Tucson Police Department responded to the scene. Some off duty policemen were recalled and assistance was given by the Sheriff's Department, Border Patrol and Highway Patrol. Some of the first arriving police officers at the scene assisted firemen in rescue operations. The police maintained perimeter and crowd control and were responsible for casualty control.

NEWS MEDIA

During the first phase of the fire, numerous people from the various news media went to the scene to take pictures and give news releases. After the fire had been brought under control, Mr. Howard Weiss, City Public Information Officer, established an Emergency Operations Center at the Police Department two blocks from the scene where members of the news media reported. From this location the dissemination of all news releases were coordinated to prevent conflicting and erroneous reporting. During the emergency the Police and Fire Communication Centers received numerous calls from news media in other cities requesting information about the fire. These requests were channeled to the Public Information Emergency Operations Center.

MEDICAL

When the "Yellow Alert" was initiated, key persons in the medical field were alerted. A command physician then reported to the scene with other doctors and a mobile medical team. At the scene they checked victims and those in need of medical attention were sent to hospitals. Those pronounced dead at the scene were taken to the County Morgue. Several of the local hospitals activated their disaster plans and were prepared to receive injured victims from the fire.

RED CROSS

Fifty volunteer and staff Red Cross disaster workers responded when notified of the hotel fire. First aid teams reported to the scene. A canteen was set up to serve firefighters and rescue workers. Some volunteers assisted at the morgue. Other Red Cross personnel offered assistance to victims who were hospitalized or housed in hotels and motels.

The Red Cross switchboard received calls from all over the country and Mexico. The majority of the calls were from Hermosillo, Mexico, as a large number of persons registered at the hotel were from that

city. Spanish-speaking volunteers assisted in answering these calls and giving assistance to the survivors who were from Mexico.

AMBULANCES

The two ambulance companies who provide the emergency ambulance service for the City responded and provided for the transportation of victims to hospitals and the morgue. These two companies utilized 11 ambulances for this operation.

FIRE DAMAGE

There was extensive fire damage to the hallways and stairways from the fourth floor through the 11th floor. One room on the sixth floor, three rooms on the eighth floor and one room on the ninth floor, including their contents, were destroyed. Other rooms from the fourth to 11th floor had extensive smoke and heat damage, as indicated by melted telephones, lamp shades, plastic articles, light bulbs, etc.

There was no structural damage to the building.

It is estimated that the fire damage to contents and building is approximately 1.5 million dollars.

DEATHS AND INJURIES

There were 28 persons who died as a result of the fire. All of these persons were occupants of rooms from the sixth floor through the 11th floor.

It is known that at least 13 persons received medical attention due to injuries from the fire. Many other occupants received first aid treatment at the scene.

There were 34 reported injuries to firefighters. Many of the reported injuries were due to smoke inhalation and overexertion. After getting fresh air and rest, these firefighters did not require medical attention. There were 19 who were taken to hospitals or treated by doctors. The most seriously injured firefighter sustained a broken pelvis. One firefighter broke his ankle, one captain had severe lacerations on his legs and one chief officer suffered severe smoke inhalation. There were seven others injured seriously enough to lose time from work. The remainder of those treated were released after being checked by a doctor.

BOARD OF INQUIRY - PIONEER HOTEL

After the fire, the Mayor appointed a Board of Inquiry, consisting of himself and two Councilmen, to investigate the Pioneer Hotel fire. Following is a copy of their report:

This Board, composed of Mayor Corbett and Councilmen Borozan and Royal, was created to inquire into the disastrous fire on December 20, 1970 at the Pioneer Hotel and, using any information derived, to take all available steps to prevent any occurrence of a similar tragedy. The Inquiry Board's activities have been supplemented by investigations conducted by the administrative staff, particularly the Fire and Police Departments. In addition, the City has had the assistance of outside consultants.

The information presented in this report does not purport to indicate liability; rather, the intent is to disclose relevant information developed by the Board through City of Tucson employees, a consultant employed by the City of Tucson, and interviews with those who had knowledge of or were witness to the fire.

City activities in the aftermath of the Pioneer Hotel fire are covered in this statement, together with a review of City actions.

RESPONSE BY CITY FORCES

Fire Department:

First notification of the fire came by public telephone to the Fire dispatch operators at 0019:15 hours reporting a car fire in the vicinity of the Pioneer Hotel. Almost simultaneously a second call at 0019:33 reported a fire on the seventh floor at the Pioneer Hotel. At 0019:45 a call from the Hotel stated there was a fire at the Pioneer on the third floor.

The following equipment was initially dispatched at 0020:29 hours; Engines 1, 2 and 3; Ladder trucks 1 and 3; and Rescue Truck 1.

Approximately one minute and 42 seconds after dispatch, Engine 1 announced to other units by radio that they would make a high-rise lay (an indication of an active fire). Engine 2 responded by announcing a similar lay nine seconds later.

Three minutes and 35 seconds after the initial dispatch, fire officers at the scene requested Fire communications personnel to dispatch additional equipment (second alarm), together with ambulances and rescue units. Engines 4 and 5; Ladder 2, and Rescue 2 were then dispatched to the Hotel.

Seven minutes after the first dispatch of fire equipment, the (third alarm) call was made, sending Engines 8, 10 and Rescue 3 to the scene.

Police Department:

At 0021 the Police radio operator dispatched officers to a reported fire at the Pioneer Hotel; the first officers arrived almost simultaneously with the first fire equipment. Upon a report of the fire's severity, other officers were dispatched to initially assist in traffic and crowd control, rescue attempts, and aid to the injured.

INVESTIGATIVE ACTIONS

Board of Inquiry

Members of the Board requested those with knowledge of the Pioneer Hotel fire to appear before it. As a result, hotel employees, together with others who were witnesses to activities concerning the fire, met with the Board. Various aspects of the fire were discussed in an effort to reconstruct related actions and events.

The Board has concluded that there is no question concerning the capable reaction and performance of the City's organizations and employees in responding to the fire and rendering aid and assistance.

Consultant's Report

Mr. Cyrillis W. Holmes from the Arson Investigation Unit of the California Division of Forestry has been retained by the City of Tucson to conduct an independent investigation of certain aspects of the fire.

As a consultant, Mr. Holmes' task was to determine the "point of origin and cause" of the fire. A preliminary report was submitted to the City Attorney on January 6, 1971. Certain related photographs (a part of Mr. Holmes' investigation) will be forwarded to the City at a later date, together with his complete and detailed final report.

The following is a summary of the preliminary reports by Mr. Holmes. In his opinion:

- The fire was intentional and man-caused, not mechanicallycaused, by some device failure and the cause is concluded to be an act of arson;
- (2) The fire had, as its point of origin, the fourth floor of the hotel, with two distinct "start" points in the fourth floor hallway, each separated from the other by approximately 60 feet;
- (3) The path of the flame spread (travel) is fairly well established by physical evidence.

Mr. Holmes' examination and investigation was conducted independently and without any knowledge that had been developed by the Tucson Fire Department or other investigators. His opinion and conclusion were based upon the physical evidence observed in and about the fire scene.

It should be noted that the Tucson Fire Department's independent study agrees with the consultant's preliminary opinions. Prior to retaining Mr. Holmes, fire officials set a fire in the unburned portion of the hotel in an attempt to establish fuel source and flame spread rate. The tests were filmed so the results could be better interpreted. Appropriate to the overall investigation, both Mr. Holmes and the Tucson Fire Department recommended further testing of certain decorating materials and furnishings used in the hotel.

Fire Department

Currently, the Fire Department is involved in an ongoing investigation of the fire. Additionally, the consultant's further findings will be available to the Fire Department for use in their investigation.

Physical evidence has been collected and is being subjected to laboratory analysis. Some of the tests are to determine fire resistance, combustion qualities, gas release, and chemical reactions of various materials.

Police Department

The Police Department continues its investigation into the arson question and all related aspects of the tragedy. The Police Department's investigation is in cooperation with that of the Fire Department.

GENERAL COMMENT

With this report, the task of the Fire Inquiry Board has been accomplished and no further action by this special body is contemplated.


In an attempt to prevent such a disastrous event in the future, legislative action will be proposed. The City's current codes conform to national standards. They can be modified to include more stringent regulations. The City, in its legislative efforts, may well consider the elimination of certain immunity from fire protection requirements and features in existing buildings. When recommendations are finalized by the City Attorney's office, Building Inspections Division, and Fire and Police Departments, they will be forwarded by the City Manager for consideration and immediate action by this Mayor and City Council.

During the Board's review, it became obvious that many citizens in this community, each in his own way, aided his fellow man in hectic moments of the fire as well as in the agonizing days which followed. This response should not go unrecognized in the otherwise technical report from this Board. The community can be proud of its people.
















ROOM 627









HALLWAY OF 4TH FLOOR




ROOM 712-- 2 CHILDREN DIED HERE.




HALLWAY OF 8TH FLOOR



ROOM 706



ROOM 1018 -CARBON MONOXIDE KILLED THE TWO OCCUPANTS OF THIS ROOM



DOOR TO ROOM ON 11TH FLOOR

MASTER NO 0459

F 7 6 6 7	T-13 7 7 7 0000	
	Lad 1.3 R-1TIME 0020	
		DAY OF WEEK Sunday
		TIME REPORTED CO19
4TH ALARM THE LL.C. 9,	27 IL. PL. TIME COUS	
5TH ALARM	TIME	PLATE NO521:6-9
6TH ALARM	TIME	DISTRICT NOO]
TOTA	AL COMPANIES	WIND DIRECTION Six
1012	ic oom Aires	M.R.H. 9 knots
ENGINE COMPANIES	2.1	TEMPERATURE 13 degrees Cahrenheit
LADDER COMPANIES		HUMIDITY 69
RESCUE UNITS		TOMOTT I
TANKERS		TATAL CIDE DECOMBE MA COTAL
HOSE WAGONS		TOTAL FIRE PERSONNEL TO SCENE
HOSE WASSIES	TOTAL COMPANIES 20	ATO THE TIME THAT ONLY A FIRE WATCH IS DECLINED AT THE
	TOTAL COMPANIES 20	(TO THE TIME THAT ONLY A FIRE WATCH IS REQUIRED AT THE
		SCENE) ON DUTY CHIEFS
ALERTS INITIATED		
YES		
PARTIAL ALERT		ON DUTY FIRE INSPECTORS
FULL ALERT	0025	CH CUTY MAINTENANCE PERSONNEL
YELLOW ALERT	017.2	ON DUTY TECH. SERV. PERSONNEL 0
RED ALERT		ON DUTY TRAINING PERSONNELO
	*	
IF YEL	LOW OR RED ALERT	TOTAL ON DUTY TO SCENE 73
	INDICATE IF:	
POLICE PROBLEM	FIRE PROBLEM X	OFF DUTY CHIEFS6
DISASTER OPERATIONS CHIE		OFF DUTY FIREFIGHTERS 67
		OFF DUTY FIRE INSPECTORS 7
FIEL	D COMMANDERS	OFF DUTY MAINTENANCE PERSONNEL 1
FIRE COMMANDED D	avless at CP at Stone & Penn	
	seler	
		OFF DOTT TRAINING PERSONNEL
COMMAND PHYSICIAN		02
	na	TOTAL OFF DUTY TO SCENE 92
	nria	2/4
	senova	TOTAL TO SCENE 165
COMMUNICATIONSE	a city or	OFF DUTY TO OTHER ASSIGNMENTS
PUBLIC INFORMATION	risa	OTT DOTT TO OTHER ROSIGNMENTS
PUBLIC INFORMATION.	risa	CHIEFS 7
PUBLIC INFORMATION	¥	
PUBLIC INFORMATION	ASSIGNMENT	CHIEFS
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont	ASSIGNMENT Interior 4.5.6 Cloors	CHIEFS
PUBLIC INFORMATION. The FIRE SECTOR COMMANDERS DuPont Rejaulti	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10.11	CHIEFS
PUBLIC INFORMATION. To FIRE SECTOR COMMANDERS DuPont Rejauli Monters	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10.11 Measuring estaging	CHIEFS
FIRE SECTOR COMMANDERS DuPont Rejacks Montage Serving	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10.11 Merzanine estaging Unper floors	CHIEFS
FIRE SECTOR COMMANDERS DuPont Rejacks Monters Source Garry	ASSIGNMENT Interior 4.5.6 floors Interior 7.3.9.10,11 Mersarine straing Unser floors Unser floors	CHIEFS
FIRE SECTOR COMMANDERS DuPont Rejarks Montage Sound Gerry Rice	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10,11 Mersarine setseing Unser floors Unser floors Unser floors	CHIEFS
FIRE SECTOR COMMANDERS DuPont Rejacks Monters Source Garry	ASSIGNMENT Interior 4.5.6 floors Interior 7.3.9.10,11 Mersarine straing Unser floors Unser floors	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 to Chief TOTAL TO OTHER ASSIGNMENTS 30 Soue
PUBLIC INFORMATION TO THE SECTOR COMMANDERS DuPont Rejarks Monters Source Garry Rice	ASSIGNMENT Interior 1.5.6 floors Apparior 2.8.9.10.11 Merzarine -staging Unner floors Unner floors Unner floors Unner floors Energy floors Appar floors Energy floors Energy floors Roving -supply and re	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 to Chief TOTAL TO OTHER ASSIGNMENTS 30 Scue TOTAL OFF DUTY MEN REPORTING 122
PUBLIC INFORMATION TO THE SECTOR COMMANDERS DuPont Rejarks Monters Source Garry Rice	Assignment Interior 1.5.6 floors Interior 7.3.9.10.11 Marsarine setseing Unner floors Uncer floors Uncer floors Uncer floors Engine supply and re	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 to Chief TOTAL TO OTHER ASSIGNMENTS 30 soue
PUBLIC INFORMATION The FIRE SECTOR COMMANDERS DuPont Rejauki Monters Source Garry Pice Amarc	ASSIGNMENT Interior 1.5.6 floors Interior 2.5.9.10.11 Merastine stasing Unper floors Unper floors Unper floors Unper floors Unper floors Unper floors Ones supply and re	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 to Chief TOTAL TO OTHER ASSIGNMENTS 30 Scue TOTAL OFF DUTY MEN REPORTING 122
PUBLIC INFORMATION TO FIRE SECTOR COMMANDERS DuPont Rejarki Monsters Soming Garry Pice Amaro Time Fire was under con	ASSIGNMENT Interior 1.5.6 floors Apparior 2.5.9.10.11 Merzarine estasing Unper floors Unper floors Unper floors Unper floors Unper floors Consequence estasion Rowing -supply and re	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 to Chief TOTAL TO OTHER ASSIGNMENTS 30 Scue TOTAL OFF DUTY MEN REPORTING 122
PUBLIC INFORMATION TO THE SECTOR COMMANDERS DuPont Rejaski Monters Supring Garry Pige Amare	ASSIGNMENT Interior 1, 5, 6 floors Interior 7, 3, 9, 10, 11 Marzarine -staging Unner floors Uncer floors Uncer floors Uncer floors Uncer floors Uncer floors Comply and re ORROL 0116 SEGAN AVE 0322	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL TO OTHER ASSIGNMENTS 30 SOLE TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS)
PUBLIC INFORMATION DEFINE SECTOR COMMANDERS DuPont. Rejaults Montanta Souther Companies Attach Time Fire was under continue companies at scene to go into service or letime all fire companies	ASSIGNMENT Interior 1.5.6 floors Interior 2.5.9.10.11 Melastine staging Unper floors Unper floors Unper floors Unper floors Unper floors Unper floors Office supply and re Office SEGAN AVE 0322	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL TO OTHER ASSIGNMENTS 30 SOLE TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203
PUBLIC INFORMATION TO PIRE SECTOR COMMANDERS DuPont Rejarks Monters Summe Gent Pige Attach	ASSIGNMENT Interior 1, 5, 6 floors Interior 7, 3, 9, 10, 11 Marzarine -staging Unner floors Uncer floors Uncer floors Uncer floors Uncer floors Uncer floors Comply and re Oli6 SEGAN AVE 0322 1450	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY)
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS Du Pont. Rejaulis Montora Sanuag Garry Pige Attare Time Fire was under contine companies at scene to go into service or letime all fire companies CLEAR OF the scene CLEAR OF the scene Du Ponto Service or letime all fire companies CLEAR OF the scene Du Ponto Service or Letar or Let	ASSIGNMENT Interior 1, 5, 6 floors Interior 7, 3, 9, 10, 11 Marzarine -staging Unner floors Uncer floors Uncer floors Uncer floors Uncer floors Uncer floors Comply and re Oli6 SEGAN AVE 0322 1450	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL TO OTHER ASSIGNMENTS 30 SOLE TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203
PUBLIC INFORMATION TO FIRE SECTOR COMMANDERS DuPont. Rejarki Monatora Somma Garry Pige Amero Time Fire was under continue companies at scene to go into service or letime all fire companies Clear of the scene Fire personnel left on	Assignment Interior 1.5.6 floors Interior 2.3.9.10.11 Merzarine -etaging Unner floors Unrer floors Unrer floors Unrer floors Enter floors Oli6 SEGAN AVE 0322 1150 FIRE WATCH YES X NO	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TO Chief TOTAL TO OTHER ASSIGNMENTS 30 SCUE TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY)
PUBLIC INFORMATION DEFINE SECTOR COMMANDERS DuPont. Rejaults Montanta Sauting Garry Pige Attach Time Fire was under continue companies at scene to go into service or letime all fire companies clear of the scene Fire personnel left on 100 attach 100 atta	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.2.10,11 Managine staging Unser floors Segan Roving -supply and re 1750 FIRE WATCH YES_X NO	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TO Chief TOTAL TO OTHER ASSIGNMENTS 30 SCUE TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY)
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont. Rejauks Monters Serving Greet Pide Attended Time Fire Was under continue companies at scene to go into service or lettime all fire companies Clear of the scene Fire personnel left on Location 80 No. St.	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10,11 Mararine staging Unner floors Unrer floors	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TO Chief TOTAL TO OTHER ASSIGNMENTS 30 SCUE TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY)
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS DUPONT. ROJANIA R	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10,11 Mararine -staging Unner floors Uncer floor	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1450 12-20-70
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS DUPONT. Rejacki Montera Secura Garry Pice Attere TIME FIRE WAS UNDER CONTIME COMPANIES AT SCENE TO GO INTO SERVICE OR LETIME ALL FIRE COMPANIES CLEAR OF THE SCENE FIRE PERSONNEL LEFT ON LOCATION 80 No. Strocker Picener Fowner Picener Type of incident Type of Inciden	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10,11 Mararine -staging Unner floors Unrer floor	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS DUPORT. ROJANIA	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10,11 Ma-varine -staging Unner floors Unrer floo	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 100 DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1250 12-20-70 COOE 63
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont Registry Registry Montors Summe Gerty Pige Atterd Time fire was under contime companies at scene to go into service or letime all fire companies clear of the scene fire personnel left on location 80 No. Stocker of the scene Fire personnel left on location Pioner Type of incident	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10.11 Mergaring straing Unser floors Unser floors Unser floors Unser floors Unser floors Unser floors Engly and re TROL 0116 SEGAN AVE 0322 1150 FIRE WATCH YES_X NO tone Ave. iotel Interprises Iding five Indiary MCY Fotel	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE FERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 COOE 01 COOE 63 COOE 119
PUBLIC INFORMATION TO PUBLIC INFORMATION TO PURPORE THE SECTOR COMMANDERS DuPont Registry Reg	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10.11 Margaring straing Under floors Under floors Under floors Under floors Poving supply and re TROL 0116 SEGAN AVE 0322 1150 FIRE WATCH YES_X NO_ tone Ave. total Interprises Iding Fire Indiary Endiary Endiary Endiary	CHIEFS 3 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE FERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 COOE 01 COOE 62 CODE 119
PUBLIC INFORMATION TO FIRE SECTOR COMMANDERS DuPont Rejarks Monters Source Garry Pige American Source Garry Pige American Source Garry Pige American Source Garry Pige Garry Pige Garry Pige Garry Pige Garry Garry Garry Garry Pige Of Incident Fire Personnel Left on Location 80 No. Stoccupant Pige of Incident Fige Figure 1 Type of Incident Figure 1 Type of Incident Figure 1 Type of Construction Fire Factor No. 1 Cal	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10.11 Marzarine setseing Under floors Under floors Under floors Under floors Poving supply and re TROL 0116 SEGAN AVE 0322 1150 FIRE WATCH YES_X NO_ tone Ave. totel Interprises Iding Five Indiery UNCY_Fotel Condinary Laved Alarm	CHIEFS 3 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE FERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 COOE 01 COOE 63 CODE 119
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS DUPONT ROJENTS MONTONE SOURCE OF LETTINE FIRE WAS UNDER CONTIME FIRE WAS UNDER CONTIME COMPANIES AT SCENE TO GO INTO SERVICE OR LETTINE ALL FIRE COMPANIES CLEAR OF THE SCENE FIRE PERSONNEL LEFT ON LOCATION 80 No. Stroccupant Pioner Power Pioner Type of incident Till Cause of ignition Troc CLASSIFICATION OF OCCUPATION TYPE OF CONSTRUCTION FIRE FACTOR NO. 1 Eal	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10.11 Margaring straing Under floors Under floors Under floors Under floors Poving supply and re TROL 0116 SEGAN AVE 0322 1150 FIRE WATCH YES_X NO_ tone Ave. total Interprises Iding Fire Indiary Endiary Endiary Endiary	CHIEFS 32 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE FERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 CODE 01 CODE 01 CODE 01 CODE 01
PUBLIC INFORMATION TO FIRE SECTOR COMMANDERS DuPont Rejarks Monters Source Gerry Pige Attended Time Fire was under continue companies at scene to go into service or lettime all fire companies clear of the scene Fire personnel left on Location 80 No. Stoccupant Pigner Former Pigner Type of incident Time Classification of occupant Type of incident Time Classification of occupant Type of construction Fire Factor No. 2 Verification to Called Fire Factor No. 2 Verification Comments of the Fac	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10.11 Merzarine estasing Under floors Under floors Under floors Under floors Editor estasion Rowing -supply and re TROL 0116 SEGAN AVE 0322 1150 FIRE WATCH YES X NO tone Ave. Sotel Interprises Uding five Editory WHOY Hotel Credinary Saved Alexa	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 CODE 01 CODE 01 CODE 02 CODE 02
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont. Rejarks Monacha Sannac Garry Pige Amero TIME FIRE WAS UNDER CONTIME COMPANIES AT SCENE TO GO INTO SERVICE OR LETIME ALL FIRE COMPANIES CLEAR OF THE SCENE FIRE PERSONNEL LEFT ON LOCATION 80 No. Stoccupant Pige of Incident Type of Incident Type of Incident Type of Incident Type of CASSIFICATION OF OCCUPATTYPE OF CONTRUCTION FIRE FACTOR No. 1 Easter Factor No. 2 Verification of CASSIFICATION OF COLUMN FIRE FACTOR No. 2 Verification of CASSIFICATION OF CASSIFICATIO	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10.11 Marzarine setseing Under floors Under floors Under floors Under floors Poving supply and re TROL 0116 SEGAN AVE 0322 1150 FIRE WATCH YES_X NO_ tone Ave. totel Interprises Iding Five Indiery UNCY_Fotel Condinary Laved Alarm	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 CODE 01 CODE 01 CODE 02 CODE 05
PUBLIC INFORMATION DEFIRE SECTOR COMMANDERS DuPont. Rejarks Monara. Square. Garry Pige American Screen Street Screen Scre	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10,11 Ma-sarine staging Unser floors Unser Unser floors Unser	CHIEFS
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont. Rejaurs Rejaurs Montage Gener Fige Amero Time fire was under contime companies at scene to go into service or lettime all fire companies clear of the scene fire personnel left on location 80 No. Stoccupant Figure 1 Type of incident 1 Type of incident 1 Type of construction 1 Cause of ignition 1 Toe classification of occupant fire factor no. 2 Voltier factor no. 2 Voltier factor no. 3 Communication 38 civil	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10,11 Ma-sarine staging Unser floors Unser Unser floors Unser	CHIEFS
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont. Rejaurs Rejaurs Montage Gener Fige Amero Time fire was under contime companies at scene to go into service or lettime all fire companies clear of the scene fire personnel left on location 80 No. Stoccupant Figure 1 Type of incident 1 Type of incident 1 Type of construction 1 Cause of ignition 1 Toe classification of occupant fire factor no. 2 Voltier factor no. 2 Voltier factor no. 3 Communication 38 civil	ASSIGNMENT Interior 1.5.6 floors Interior 2.3.9.10,11 Ma-sarine staging Unser floors Unser Unser floors Unser	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YES. HOW LONG 1450 12-20-70 CODE 63 CODE 149 CODE 04 CODE 05 EDILLDING CONTENTS VALUE OF 8.000,000,00 4,000,000 LOSS TO 1,000,000,00 500,000,00
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS DUPORT ROJECULA SOURCE CARROLL SECTION DE FIRE PERSONNEL LEFT ON LOCATION BO No. SECTION OCCUPANT PIONEER PIONEER PIONEER PIONEER PIONEER PIONEER PERSONNEL LEFT ON LOCATION BO No. SECTION OCCUPANT PIONEER PION	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10,11 Margarine -staging Unner floors Unrer water Unrer water Unrer prises Unding five Unrer floors Unrer prises Unrer floors Unrer prises Unrer floors Unred floors Unrer floors Unrer floors Unrer floors Unrer floors Unred floors Unrer floors	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1250 12-20-70 CODE 01 CODE 01 CODE 02 CODE 05 BUILDING CONTENTS VALUE OF 8.000,000,000 1,000,000
PUBLIC INFORMATION FIRE SECTOR COMMANDERS DuPont. Rejaurs Rejaurs Montage Gener Fige Amero Time fire was under contime companies at scene to go into service or lettime all fire companies clear of the scene fire personnel left on location 80 No. Stoccupant Figure 1 Type of incident 1 Type of incident 1 Type of construction 1 Cause of ignition 1 Toe classification of occupant fire factor no. 2 Voltier factor no. 2 Voltier factor no. 3 Communication 38 civil	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10.11 Marzarine estaging Unner floors Uncer floo	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE 8 TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YESHOW LONG 1150 12-20-70 CODE 01 CODE 02 CODE 05 BUILDING CONTENTS VALUE OF 8 CCO. OCO. OCO. CO LOSS TO 1.000,000.00 5CO. CCO. CO INSURANCE X. YES NO X.YES NO
PUBLIC INFORMATION DE FIRE SECTOR COMMANDERS DUPORT ROJECULA SOURCE CARROLL SECTION DE FIRE PERSONNEL LEFT ON LOCATION BO No. SECTION OCCUPANT PIONEER PIONEER PIONEER PIONEER PIONEER PIONEER PERSONNEL LEFT ON LOCATION BO No. SECTION OCCUPANT PIONEER PION	ASSIGNMENT Interior 1.5.6 floors Interior 7.3.9.10.11 Marzarine estaging Unner floors Uncer floo	CHIEFS 7 FIREFIGHTERS 22 FIRE INSPECTORS 1 MAINTENANCE PERSONNEL 0 TECH. SERV. PERSONNEL 0 TRAINING PERSONNEL 0 TOTAL OFF DUTY MEN REPORTING 122 (TO SCENE AND OTHER ASSIGNMENTS) TOTAL ON DUTY NOT AT THE SCENE TOTAL ALL FIRE PERSONNEL 203 (ON DUTY AND OFF DUTY WHO REPORTED TO DUTY) IF YES. HOW LONG 1450 12-20-70 CODE 63 CODE 149 CODE 04 CODE 05 EDILLDING CONTENTS VALUE OF 8.000,000,00 4,000,000 LOSS TO 1,000,000,00 500,000,00

RESPONSE

RE COMMANDER	Bayless	FII	RE COMMANDER'S A	NOE Rakow (fro	E-10)
STRICT NO I CHIEF	Duffert. Rojeski	DI:	STRICT NOT CHIEF'S	S ALDE Abodeca	
					Ladder 3
FIRE CO NO	_Eogire 1	Engine 2	Engine 3	Ladder 1	
DISPATCH TIME	0020	<u>C020</u>	0050	The second secon	0020
THE PARTY AND ADDRESS OF THE PARTY OF THE PA		C0S5	0025	0022	0027
TIME IN SERVICE	0300	11,50	0651	01,00	0519
IME LEAVING SCENE	<u>C653</u>	1450	0610	Olico	0519
HLEAGE TO SCENE	0.2	0.2	1.9	0.8	4.3
PUMP TIME	5.9 hrs	7.3 hrs	3.0 hrs	0	
FEET OF LADDER	0	38 ft	2/154	19hft	130ft
I INCH HOSE	0	0		0	0
1 1/2 INCH HOSE	200 ft	LCO ft	00	0	3.60
2 1/2 INCH HOSE	1500 ft	400 ft	2000 ft	0	0
3 INCH HOSE	0	0	0	100ft	0
GALLONS USED	30,000 gals		15,000 gals_	0	6000gals (1
	C	MEN RESPO		Towns	
CAPTAIN	Carranza		Schoup	Jones	Sedlack
	Adams, C.	Brunning	Cook, P.	Foster	Danielson
	Lopez, R.	Wray	Hall	Seal	Temavo
	Delahanty	Banton	White	Romero	Burns
	Cock, C.	Konigsfeld		Harmel.	Shipman
				Edwards	
FIRE CO NO	Resone 1	Engine 5	Engine 7	Ladder 2	Rascue 2
DISPATCH TIME	0020	0025	0025	0025	0025
TIME AT SCENE	Dose	0032	0030	0030	0030
TIME IN SERVICE	C505	0332	01:37	CFCO	Olico
ME LEAVING SCENE	0505	0332	OL:37	OFCO	Otico
ILEAGE TO SCENE	0.2	3.8	3.5	3.5	3.5
PUMP TIME	0.4	With the Party of	0	0	
	0	0	- 2Lft	16526	0
FEET OF LADDER	0	0	0	0	0
I INCH HOSE	0		0	0	
1 1/2 INCH HOSE		100ft			0
2 1/2 INCH HOSE	0	50rt	0	0	0
3 INCH HOSE	0	0	0	0	0
GALLONS USED	0	0	0	0	0
CAPTAIN		Jensen	ONDING Regilio	Machado	Trufillo
CAPTAIN		A STREET, SQUARE OF STREET, SQUARE S	Felix	Management of the Park Street, and the Park Street, St	17031110
	Wise	Harris	Second State of Second	Rowsee	
		_	Wilder	Arriaga	
		Craves	Berlina	Pesquera, J	
				Cook, W. H.	
FIRE CO NO	Engine 8	Engine 10	Rescue 3	Rescue 5	Engine 4
DISPATCH TIME	0026	3500	0028	0028	COl:5
TIME AT SCENE	0035	0031:	003h	0036	CO75
TIME IN SERVICE	0355	Ch23	0/153	0355	0338
IME LEAVING SCENE	0355	01:23	01:23	0355	0338
HLEAGE TO SCENE	4.0	4.3	11.3	Li.O	1.5
	0	0	0	0	0
PUMP TIM E			0	0	0
PUMP TIM E FEET OF LADDER	0	0			The state of the s
		0	0	0	0
FEET OF LADDER	0		0	0	looft
FEET OF LADDER I INCH HOSE I 1/2 INCH HOSE	0 0 2001t	0	-		looft
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE	0	0 0 Sort	0 0	0	100ft 100ft
FEET OF LADDER I INCH HOSE I 1/2 INCH HOSE	0 0 2007t 501t	0	0	0	looft
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	0 0 2COTE 5CET 0	0 0 50ft 0 0 0 MEN RESP	0 0 0 0	0	100ft 100ft 0
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE	0 0 2007t 507t 0 0	0 0 50rt 0 0 MEN RESP Branaman, D.	0 0 0 0	0	100ft 100ft 0
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	0 0 2COTE 5CET 0	0 0 50rt 0 0 MEN RESP Branaman, D.	0 0 0 0	0 0	100ft 100ft 0
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	0 0 2007t 507t 0 0	0 0 50rt 0 0 MEN RESP Branaman, D.	0 0 0 0	0	100ft 100ft 0 0
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	0 0 2Cort 5Crt 0 0	O O SOFT O O O MEN RESP Branaman, D. Rakow	0 0 0 0	0 0	100ft 100ft 0 0 0 McGarty Steamen Soulvie
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	O O O O O O O O O O O O O O O O O O O	O O SOFT O O MEN RESP Branaman, D. Rakov Engelkes	0 0 0 0	0 0	100ft 100ft 0 0 0 McGarty Steamen
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	O O O O O O O O O O O O O O O O O O O	O O SOFT O O MEN RESP Branaman, D. Rakov Engelkes	0 0 0 0	0 0	100ft 100ft 0 0 0 McGarty Steaman Soulvie
FEET OF LADDER I INCH HOSE I I/2 INCH HOSE 2 I/2 INCH HOSE 3 INCH HOSE GALLONS USED	O O O O O O O O O O O O O O O O O O O	O O SOFT O O MEN RESP Branaman, D. Rakov Engelkes	0 0 0 0	0 0	100ft 100ft 0 0 0 McGarty Steaman Soulvie

1 500 00 00	- 6	Engine 9	Saging 11 .	Invar b	
FIRE CO NO	- 1 1 1 1 1 m				
DISPATCH TIME	(7)5	cohg	0015	COLS	0355
TIME AT SCENE	CONS	COER	0050	0058	CD.22
TIME IN SERVICE	0351	035%	Chil	0354	0352
	the rate of the same of the sa		0,50	0354	0333
TIME LEAVING SCENE	0351	0354	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	SECURITION AND DESCRIPTION OF THE PERSON NAMED IN	Bernard Andrew Strategy and Company
MILEAGE TO SCENE	6.0	7.6	5.0	7.6 .	0
I PUMP TIME	0	0	0	0	0
FEET OF LADDER	0	0	0	0	0
The second secon	0	British Colored Colore	0		The state of the s
I INCH HOSE	-	0		0	0
I 1/2 INCH HOSE	300ft	100ft	0	0	0
2 1/2 INCH HOSE	0	100ft	50ft	0	0
	0	0	0	U	0
3 INCH HOSE				0	
GALLONS USED	0	0	0	U	0
1		MEN RE	SPONDING		1
CAPTAIN	Facio	Grines	Moran		Carpenter
CAPTAIN	-		Wells	Cox	Kanvur
1	Solomon	Hopos		-	Nenver
•	Longtin	Sisk	Grienser	Uthe	
1	Vanzandt,	Cox	Bell, E.H.		
1					
1					
}					
•	WALLES THE STREET OF THE STREET	AND A PROPERTY OF THE PARTY OF		1	_
•				Marie - Charles Carrell	
1					
		11711	ITY TRUCKS		
2.				TOMES ETC	,
(6	MAINTENANCE	TRUCKS, 5000	WATT LIGHT PLANT	IMAILEN, EIG.	
			01.66		
TRUCK NO.	618	2136	Lilent Plant		
DRIVER	Murtha	Price	Price		
			TOTALS		
•:		-			
			RESCUE UNITS 5	HOCE	WACONE O
ENGINE COS. 11	LADDER CO		RESCUE UNITS	HUSE	WAGONS 0
TANKERS 0	CHIEF OFFIC	ERS 3	FIRE PERSONNEL 69	UTILIT	TY TRUCKS 2
LIGHT PLANT TLRS. 1			1 1		
LIGHT FEART TERS		18			
TOTAL PUMP TIME	15.1 T	OTAL HOSE USE	0 1" 1		USED IN FEET
04 I			1 1/2" 11.000t A	ERIAL 285 f	t
			2 1/2" 1/300ft		
the second secon			2 1/2	IAND 270ft	**
EST. WATER USED	IZI, COO gais		3" 100ft H	AND LICE	
		5.6	UTUAL AID		
		- 1/2	OTOAL AID		
		and the same and t			
	YES NO NO. M	EN EQUP	MENT	SERVICE PR	OVIDED respended en
DAVIS MONTHAN	xls	500 col r	ourner Sto	od by at San	tion 9 I call
HUGHES AIRCRAFT		750 and p	numer Sto	on by ot Sta	tion Th
		7000 007	pumpou, 750 Sto		Tuesen Fire Station
50. 10030N F. D	x 12		The state of the s	ou by 111 bo.	AROSCH FARM DVELLO
		Bar and c	old gai pumper		
			CTUED ACENCIES	00 050505	10
	ASSISI	ANCE FROM	OTHER AGENCIES	OR PERSUI	13
	1050 00000	C D FOOD DO	NATIONS, AMBULAN	CE COMPANIES	ETC \
	(RED CROSS,	C.D., FOOD OC	MATIONS, AMBULAN	SE COMPANIES	, 610.7
	NO.				
AGENCY/PERSON	PERSONS F	QUIPMENT	SERV	ICE PROVID	fee, acsisted
Red Cross	PERSONS E	Vahiele wit	h cood havided	igod, and cer	fee, assisted
1100 01000	no an End Oress	2 13	11 2004 11 21 21		R. (1 10220
Command Phys.	d Found	na rnys, and r	1001Te menicat resu		
C.D.	20 2 Ros	one and Comm.	vehiles Stood b	y at Command	Post
A&A Amoulance Co.		ulances		ed victims	
Kords Ambulance Co.	THE RESERVE AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED I		The same is a second district to the same is a second district ton	ed victims	
		ulances			
Flowing Weile Fire 1	10		Steed by in c	age they were	e reeded
	21				
-					
-					
					AND THE RESERVE OF THE PARTY OF
		OTUED O	ITY DEDARTMENT	re	
		OTHER C	ITY DEPARTMENT	S	
Parameter and a second		-	ITY DEPARTMENT	rs_	
DEPARTMENT	PERSONS 1.CO	-	ITY DEPARTMENT		
	PERSONS LISOS	QUIPMENT	SERVICE P	ROVIDED	
DEPARTMENT Streets		QUIPMENT		ROVIDED	t the scene
		QUIPMENT	SERVICE P	ROVIDED	t the scene
		QUIPMENT	SERVICE P	ROVIDED	t the scene
		QUIPMENT	SERVICE P	ROVIDED	t the scene
		QUIPMENT	SERVICE P	ROVIDED	t the scene
		QUIPMENT	SERVICE P	ROVIDED	t the scene

EQUIPMENT AND TOOLS USED

	IND	CAT	E N		BER (ANE					ISE															
COMPANY NO-	ALE	AIR BOTTI FS	AXES	BLANKETS	SOLT	CLAN TOOL	DEL UGE SET	HAND LIGHTS	HOSE ROLLER	45FT EXTENSION	35FT EXTENSION	PARTE EXTENSION	OFT EXTENSION	TOUR HOOF	HALDER	14FT ROOF	TOST FOLDING	14FT STRAIGHT	LADOER	25FT STRAIGHT	ZRET STRAIGHT	LADDER	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PONTABLE CUTTING TORCH	POSTABLE	PORTABLE	RESUSCITATORS	SNOKE	SALVAGE
Eng. 1	12	6		1				2	1			ì	1	T	:		-	1	1	1	-	-	-		1	1	-	-	-
Bng. 2	12	8	1	2				2			1	11	1			1		1		1		-	-	-	-	1	-		_
Eng. 3	2	2	2			2		2				1					1					-				-			
Eng. 4	12	14		1				2										1		1					-				_
Eng. 5	2	14						5							1		1	T								1			-
Eng 6	2	11													1							_		1					1000
Eng. 7	2	6						5		9		1						1				-				1			-
Eng. 8	2	5										1															1		_
Eng. 9	3	7						2															7						
Eng. 10	2	6						2															-				-		
Eng. 11	2	1						2																					-
Lad. 1	6	10	6	1				1		1	1					1						1				17	3		-
Lad. 2	5	12	5				i	1		1													1			1	1		
Lad. 3	5	10	5	1				3	1		?				-		1						2			1	1		_
Lad. lt	2	2					i																						_
Rescue 1			_	3		_ 1																					1		_
Rescue 2	1	1						2																			1		
Rescue 3						!																					1		
Rescue 4											1																		_
Rescue 5		1					_									200											1		_
TOTALS	43	90	19	12	01	2	0	31	1	- 2	2	3	0	0	0	2	1	0	0	0	0	1	4	Ü	0	I	ठ	0	C

COMPANY NO. Eng. 1 Eng. 2 Eng. 3 Eng. 4 Eng. 5 Eng. 6 Eng. 7 Eng. 8 Eng. 9	Shovels	Life Relt	Oxygen Bottle	First Aid Kit	Litter Pasket	Splints	Pike Poles	23, Fog Nez																					
Eng. 1	-	-					-			_	-	+	-	-	-	-	-	-		-	-	-	-	-	-	-		_	
Eng. 2	-									_		+	-	-	-	-	-	-	-	-		-	-	-	+-	-		-	_
Eng. 3	1					-		_		-	-	-	-	-	-	-	-	-	+-	-	_	-	-	-	-	-	-		
Eng. h	1									- 8		-	1	-	-	-	-	-	-	-	-	-	-	-	+-	-	-		
Eng. 5						-						1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		_	_
Eng. 6			7 - 5							_		1	1	1	-	-	+	+-	-	-	_	-	-	-	-	-			_
Eng. 7												-	1	-	1	+		-	-	-	-	-	-	-	+-	-			_
Eng. 8												1	1	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Eng. 9												1	1	-	1	-	-	-	1				-	-	-	-		-	
Eng.10								7						1		1	-		-				-	-	1	-	-	-	_
Eng.11												-				1		1	1		_	-	-		-	-			_
Lad. I		1	3	1						7.5		1	-	-	1	1	-	1	-	_	-		-	-	-	-			-
Eng.10 Eng.11 Lad. 1		1	3								-		-	1	-	+-		1			-	-		-	-	1		-	
Lad. 3		1	1				1							1		1		1		_				-	-			-	_
Lad. L															1		1	_	1				-		i	-			_
Rescue 1		9	3	1		3								1			1	1	1						-			1	
Rescue 2														1	-			-		-		_	_		1	-		-	-
Rescue 3												-		-		-		-	-				_	-	-	-		-	- 20
Rescue h														-	 	-	-			-		-			-	-		-	-
Rescue 5													-	-	-	-			-	-	-		-	-	-		-	-	_
TOTALS	1	3	10	2	0	31	1	71	-		-	-		-	-	-	-	-	-	-	-	-	_	_	-	-	-	-	-
The same of the last of the la	-		-	Allen A	-					-	-	-	-	-	Linera	Longo					-				-		-		-

•		(OFF BUTY R BIR (
	TIME		PERFORMEL REPORTING
mant	10 000 1	LIEVED	ASSESSMENT _
CHIEF OFFICERS			
Peterson	0030	0830	To the scene Disaster Operations Chief
Dirks	0100	0830	To station #1 In charge of operations at stat. 1
Sprung	03.00	0570	To the scene
Rice	0105	0600	To the scene
Dearing	0110	0900	To station #1 To the scene at 0530
Slagel	0115	1700	To station #1 - To the scene at 0300
Cliver	0045	_0500_	To the scene
Russell	0030	6700	To station 9 - Filled in as District #2 Chief
Elins	0116	0650	To station 1, to So. Tucson F.D, then to scene
Hansen	0110	0800	To station 1, to the scape at approx. 0330 To station 1, to communications at approx. 0230
Amaro		0000	To the scene
Monteya	0050	0630	To the scene, in charge of staging area
Art			to one books, in that to the boarding area
	To the Sce	ene 6	Other Assignment 7 TOTAL CHIEFS REPORTING 13
CARE INSPECTORS	07.00	3/00	m
Gilmore Franklin	0100	1630	To the scene
	0025	0210	To the scene
Sweggrd I.P. Combath	0030	0630_	To the scene
W. J. Martin	0117	0806_	To station 114 as Laison Officer with Hughes, then to see
Armstrong	0100	1630	To the scene
McGoe	0100	0845	To the scene
Shumaker	01.00	0600	To the scene
			The state of the s
To the Scene	7 Other	Assign	rment 1 TOTAL FIRE INSPECTORS REPORTING 8
TRAINING PERSONNEL			
Gregory Coens	0030	0830	To the scene
Deschaines	07.39	0830	To the scone
Kelly	0135	0830	. To the scene
Glen		0830	To the score
Zielbauer	01/15	C830	To the scene
Schreiber	0.125	0830	To the scepe
LeCompto	0136	0830	To the scene
Pierpent	0315	0730	To station 1 later to the scene
Frana .	0050	0830	To the scare
Cirivello	<u> </u>	0830	To the scone

			*
			Management and the state of the
			· · · · · · · · · · · · · · · · · · ·
		r Assi	grant O TOTAL TRAINING PERSONNEL REPORTING 11
MAINTENANCE PERSON			
Price	0100	0630	To the scene
o the Scene 1	Other Assim	ment (TOTAL MAINTENANCE PERSONNEL REPORTING 1
TECHNICAL SERVICES		-	The second of th
c the acc c 0 (Her ashiph.	0	TOTAL TECHNICAL SLAVICES PERSONNEL REPORTING 0
Welbern COMMUNICA			E- 0
	0100	0100	To Communications Center
Eaton		0100	To Communications Center
Larzon	0055	01.20	To Courunications Conter
Adsaler	0055	0600	Technicism to Communications Center
Penus	0115	0000	Technician to the Scene, with service truck
To the Come 1	To Commo	ent	L TOTAL ROTATION ATION: PERSONNEL REPORTING 5
The second second	LO GOMES O	chier.	4 Danie Description at Rolls Deliction 1, 30 Port 166 5

		V
	TIME	
NAME	TO DULL BURNE	D ACCOUNTERY
1_Abits	0022 0230	To the scene
figurality Co Ire	C100 0730	To the game
3 Adame, H. M.	0123 0800	To the scena
4 Aguiler, R. M.	0230 0600	To the scene
5_Archiald	0150 0600	To the scene
6 Page	0700	To station 1, manned Reserve Eng. 1
7 Baldwin, R.C.	0122 0815	To the scene
Bernes, A. J.	0159 0700	To station 1, manned Reserve Lad. 1
9 Bellagyer, W. M.	0300 0745	To station 1, manned Reserve Lad. 1
11 Boyla, Bruce B.	0152 0700	TO big scene
12 Brothour	0220 0800 0210 0500	To station 1, manned Reserve Eng. 1
13 Briggs	0227 0300	. To the scene
14 Brown, K. W.	0130 0500	To the scene
15 Cammarano	0100 0530	To the scene with Reserve Engine 2505
16 Carrillo	0459 0610	To the scope with Reserve Engine 8027
	01000715_	To the scene with Reserve, Engine 2505
	0110 0610	To the scene
19 Clodfelter	0123 0610	To the scene with Reserve Engine 2505
	0105 0800	To the scene To the scene
21 Crewford	0235 0600	To the scene
22 Davis, Jimay	0110 0860	To the scene with Reserve Engine 8027
23 Dina, C. V.	0200 0800	To the Scene with Reserve Lighte 6027
	03.30 0500	To station 1, manned Pesarve Eng. 2 To the scens
	0125 610	To the scene with Reserve Engine 2523
26 Discher	0200 0800	To station 1, manned Reserve Lad. 1
	0200 0530	To station 1, then to scene
28 Fimbres	0150 0818	To the scene
29 Furan	0140 0830	To the scene
30 Gallerdo	0242 0600	To the scope
of Grace	0200 0700	To the scene
32 Grachem	0032 0702	To the scene
33 Groat	titles there	To the scene
34 Harrison	0220 0800	To station #1, named Peserve Eng. 1
35 Hert	0105 0705	To station #5. Hanned Reserve Eng. 5
36 heverly	0155 0700	To the scene
37 Highhouse	0100 0600	To the scene with Reserve Engine 2523
38 Highern	0100 0705	To station #5, manned Reserve Eng. 5
39 Eophing	01000700_	To the scene with Reserve Engine 2023
40 Kavelon	0110 0600	To station 1, then to Sc. Tucson F.D. as Laigon Officer
41 Keller	0225 0820	10 did scene
42 Kepler	0130 0700	To station #5, manned Reserve Eng. 5
43 Ketchen	0150 0318	To the scene
44 Kwart	0215 0815	To the scene
45 Leoui	0130 0630	To the scene
46 Lacn, Rudy	0145 0700	To station #1, manned Reserve Eng. 2
47 Lopez, A. G. 48 Lujen	0200 0600	To the scene
49 Mackey	0100 0600	To the scene with Reserve Engine 8027
50 Hantornach	0120 0610	To the scene with Reserve Engine 2405
51 Martin, J. D.	9215 0715 0152 0700	10 Ing scene
52 May	BUTCHES HER TON THE BUTCHES STREET THE PERSON NAMED IN	To the scane
53 Mazon	0110 0730 0045 0800	To the scene
54 McAnally	0120 0730	To the scene with Reserve Engine 8027
55 McAdana	0109 0709	To the scene
Sc_McDonald	0220 0300	To station #5, manned Reserve Eng. 5
57 Montano	0100 0500	To the scene
50 Boreno , Gue	0100 0610	To the scene
59 McCulloch	0235 0815	To the scene with Reserve Engine 2523 To the scene
co Moltrier	0128 0900	To the scene
G I Mowday	0115 0600	To the scene
G2 Murtha	0145 0800	To station #1, manned Reserve Eng. 2
63 Palko	0130 0610	To the scene with Reserve Engine 5027
64 Perez	0200 0500	To the scene
65 Perry	0300 0700	To the scene
66 Pesqueira	0227 0600	To the grave
67 Plummer	01.30 0630	To the scene
68 Poling	0115 0715	To the scene
Putney, John H.	0235 0810	_10_DDa_scena
70 Queirnga	0200 0700	To station #1, nammed Reserve Eng. 2
To the Scene oc	ent. Other Assis	prent cont. 101AL continued
		(IF ALL ARE LEGIC MALL CO.

(IF ALL APP LETTE AND A TALE OF

		TIME TO DUTY	DELIEVED	ASSIGNMENT
71 Ra			0700	To the scene
72 Ro			0800	To the scene with Reserve Engine 8027
			0700	To Station #1, manned Reserve Lad: 1
	gers, Floyd R.	0130	0630	To the scene
		0100	0300	To the scene
	Irado	0152	0700	To the scene
	COMPANY OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	0145	0300	To station #1, manned Reserve Lad. 1
	Control of the Contro		_0500_	16 the scene
A APPROXIMENT	CONTRACTOR OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	0145	07CO	To the scene
	<u>lceley</u>	0200	0800	To station #1, manned Reserve Eng. 2 To the scene with Reserve Engine 2505
	rickling	0122	0800	To station fl, manned Pererye Eng. 1
	utz bayri	0235	0600	To the scene
	n Auken	0500	0300	To station #1, manned Reserve Lad. 1
	lasco	0245	0800	To the scene
Section 100	rove	0110	0845	To the scene
	blonski	0205	0510	To station #1. manned Reserve Eng. 1
86 Zu	niga, Rorelio Ve		0610	To station 9, acted as Laisen Officer with DM Fire Dept
89 T	oci, Carson	0210	0500	To the scene
90	I A STATE OF THE S			
91			****	
92				
				Kennenger
-		-		
-				
-				
98			-	

-			-	
-				
			-	
105				
106			-	(A)
110		-		
- more				
Same				
-				
117				
118				
119				
		CA PROPERTY OF THE PARTY OF THE		
111111111111111111				
125				
129				
130				
131				


136				
138			-	
				A SUCK APPROXIMENT CONTRACTOR OF THE PROPERTY
140				0.4
To t	the Scene 67 Other	r Assign	ment 2	2 SET DUST FIRE SHAPE CSION PERSONNEL TOTAL 89
			-	


REMAININ DEFENSES OF CITY DURING PERGENCY


PLATOON DISTRICT I	CONO	I C	HIE	DER	Dearin bliss	<u> </u>			DISTRIC	T NO 2 CHIEF Cliver
NOITATE	TUS NO	OFF DUTY CRE	VACADAL	COMPANY	APP APPAR	TYPE OF ARATUS OR RATUS NO.	NUMBER OF MEN	MUT	OR UAL CO.	IF RESPONDING ON FIRE CALL DURING THE EMERGENCY - GIVE REPORT NUMBER AND TYPE OF CALL
ī		71	+	REL RE2	2502 2523 2510	1000 pump 500 pump liose Tagon	5	0200	0000	161 0107 to 0135 Rescue 12 dif. breathin 162 0112 to 0202 Rescue 12 auto accident
3			1					-		
4			12							
5 6 7		×	3	1	2503	1000 Fump	_ lı	0140	0705	Wh6h 0301 to 031h Res. E-5 Invertigate sa
8		#	2							
9		-	25	DMI	Unit 1	4 500 pum	5	0111	01:20	#1:63 0231: to 0250 DM unit Erush Fire
3			-	1	011.20	La joo pain	-	- Caract	Disco	#h60 C026 to 0155 Rescue 4 need for exyger
10	1.			ELL	25h2 75	0 pump	L			7465 Ch22 to Ch37 E-1h Investigate speke
11			13							
	X		-				-			
14	-	-	X	Corr	1000	al pumper	11	011:0	0500	
TUCSON	-		2	577	750 0	1 pumper	1	0750		
1003014	-	_				d. rumper	11		0431	
	-		-	1		1 1 1 1 1 1 1 1 1		0.21.0	101472	
			1							
	-		+							
DAVIS MO HUGHES AII	NT	HAN	I F	IRE D	EPART ME	NY Cap	tain	Li Rogeli	eison o Zuni	Officers 0000 Kayeloh 0230 to 0431
Mantsel Mantsel Martin McCace Stone,	h ez			_NA	<u>ни</u> С	OF CREW GHES Garl Outton esl, Teny utz, Eob	MEN	IBERS	Duc Yor Och	MUTUAL AID COMPANIES I TUCSON heney Engineer k Engineer otorena - Chief rono - Asst Chief
									Mor Vel Pac Crt	ales, Tino - Capt asquez hado
Total me	n	ire	et. 1	X _1	То	tal nen fro				And Personnel Reporting 20


Total Natural And Personnel Reporting 20


	MILEDI VILETARIO	1		
NAME_	WHER' TREATED	STATUS	TYPE	TIME
The state of the s	(DRS WALL CR HOSP)	(IN HOSP, BACK TO KUTY, HOME, ETC.)	OF INJURY	LOST
Adams, Chester	Dr. Wabo		Strained back	3 days
	None	O.K. for duty	Strained shoulder	none
Aproaga, Arthur	St. Mary's Hosp.	I day in hespital .	Broken Ankle	-24
Bell, E. H.	None	O.K. for duty	Smoke Inhalation	none
Choic, Ellis	Dr. Gald	Checked and sent hone	Smoke Inhalation	8 days
	Carl Hayden	Checked and released	Strained back	none
Cox Yours	None	O.K. fer duty	Bruised foot	none
Cox, Mercus	St. Mary's Hosp.	Checked and released	Snoke Inhalation	none
	Dr. Martin	Checked and sent home	Smoke Inhalation	2 days
Curningnam, barry A.	None	O.K. for duty	Smoke Inhalation	none
	Ir, Bacus	Checked and released	Strained back	none
EuPont, W. P.	Lione	C.K.for duty	Smoke Inhalation	none
Foster, V. S.	None	C.K. for duty	Smoke Irha attion	none
Greecer, Alvin B.	Kone	CoK, for duty	Strained back	nens
Franklin, Ellis	THE - Dr Edwards	1 day in hospital	Cuts and strains	4
Harmol, Charles	None	O.K. for duty	Stoke Inhalation	none
Harris, Vack	THC	l day in hospital	Smoke Inhalation	none
Jones, P. W.	Carl hayden	Checked and released	Strained back	
Jacone. C. J.	None	O.K. for duty	Smoke Inhalation	none
Konigsielů, Dale	None	O.K. for duty	Smoke Inhalation	none
	None	O.K. for duty	Smoke Inhalation	none
Lorez, Localio	Command Phys.	Checked and released	Smoke Inhalation	none
Morene, Gus	Dr. Frankel	Checked and sent home	Sprained R, ankle	10 days
Romero, Rani A.	None	C.K. for duty	Smoke Inhalation	none
Strand, Remold	V.A. Hosp. Miner	l day in hospital	Smoke Inhalation	2 days
Stedman, George	Carl Hayden	Checked and sent home	Strained back	L days
Spreng, Fred	TMC	l day in hespital	Smoke Inhalation	20 days
Seal, Fred	None	O.K. for duty	Smoke Inhalation	none
Tamavo, Frank A. Trujille. Pedro	St. Mary's Hosp.	Checked and sent home	Smoke inhalation	none
Wise, Torry D.	St. "ary's Hosp.	In hospital	Broken Felvis	*
	None		Smoke Inhalation	none
Wray, Reether Davis, David L.	Kone	U.K. for duty	Emoke Inhalation	none
	Dr. Parsons		wer Emertion	none
Edwards, Louglas	St. Mary's Hosp.	Checked and released	Smoke Inhalation	none
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7]
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	
		*Still off duty with	injury as of 1-19-7	












TOI BUSTAMANTE, JOSEFINA
TOS ANCHETA, MANUEL
TOB ARNETT, DONALD
TIO BORDWELL, WILLIAM
TI2 SOTO, HUMBERTO
SOTO, IGNACIO
TI4 ASHURST, EDWARD
TI6 DORNER, LYDIA
T22 SOTO, HUMBERTO
UNINJURED



RMNO NAME


802 GONZALES, MARIA
803 ANTILLON, JAVIER
ANTILLON, MARTIN
ANTILLON, CATALINA
ANTILLON, IGNACIA
806 SIGNS, EFFIE
809 FORD, OR 8 MRS W. H
810 SOUERS, EDITH
822 MAC LAURY, RICHARD


807 GONZALES, MARIA
808 SIGNS, EFFIE
809 FORD, OR 8 MRS W. H
810 SOUERS, EDITH
822 MAC LAURY, RICHARD

UNINJURED


UNINJURED

UNINJURED





IOO3 D'HEDOUVILLE, PAUL DECEASED CARBON MONOXIDE POISONING
IOO9 DALE, VELMA DECEASED CARBON MONOXIDE POISONING
BOND, BERNICE DECEASED CARBON MONOXIDE POISONING
IOII KAUFMAN, ESTELLE DECEASED CARBON MONOXIDE POISONING
IOI8/20 SMELSER, D.P. DECEASED CARBON MONOXIDE POISONING
IOOROON, ELLA DECEASED CARBON MONOXIDE POISONING
IOO22 TOLLEFESON, UNINJURED



RM.NO. NAME STATUS.

IIOI/IIOS STEINFELD, HAROLD STEINFELD, MARGARET DECEASED - CARBON MONOXIDE POISONING DECEASED - SMOKE INHALATION DECEASED - SMOKE INHALATION DECEASED - CARBON MONOXIDE POISONING DECEASED - CARBON MONOXIDE POISONI

DETAIL OF COMPANY ACTIVITIES

The following information was compiled from the company reports completed by each company captain. This report includes the initial action and some of the highlights of each company's activities as they fought the hotel fire. During the entire operation at the fire, companies were involved in many firefighting and rescue activities covering all floors of the hotel.

1ST ALARM

At 0020:29 the 1st alarm was dispatched. The initial response consisted of Engines 1, 2, and 3; Ladders 1 and 3; and Rescue 1.

Engine 1

When Engine 1 arrived at the scene, Captain Carranza reported that there was considerable smoke rolling out of the windows on the Stone Avenue side of the hotel. The crew of Engine 1 made a high rise lay on the Stone Avenue side of the building and connected two 2-1/2 inch lines into the Fire Department wet standpipe connection on the northwest corner of the building. Engine 1 then pumped from the hydrant on Stone Avenue approximately 200 feet north of the hotel. Later they pumped an additional two lines which supplied the ladder pipe on Ladder 1.

Chief Dupont went with Captain Carranza and two members of the crew into the hotel. The crew took two sections of 1-1/2 inch hose and nozzles with them. Upon entering the hotel the crew noted that the people in the lobby were in a state of confusion. Captain Carranza asked the elevator girl if she knew where the fire was. She stated that it was on the fourth floor. Captain Carranza then had the elevator girl take the crew and equipment to the third floor and then instructed her to return to the lobby and not to use the elevator again. The crew found much heat and smoke on the third floor. They proceeded to the north stairwell and found it was fully involved. The crew of Engine 1 used the hose from the interior wet standpipe and made the initial attack on the fire at this point about one to two minutes after their arrival. They advanced up the stairway and attacked the fire on the fourth floor.

A man came up to Captain Carranza and informed him that there was a fire at the center stairwell. Captain Carranza took a hose line from another interior hose cabinet on the third floor and attacked the fire in the center stairwell working his way up to fourth floor. He rescued a female occupant from the fourth floor and took her to the lobby. He also checked the rooms on the third floor. Some of these rooms were occupied and these people were safely evacuated.

Engine 2

Engine 2 arrived at the same time as Engine 1. Captain Jacome reported large amounts of smoke coming from several windows on the west and southside of the building. Engine 2 made a high rise lay and a two-line reverse lay to the dry standpipes on the Pennington side of the hotel. The crew of Engine 2 took lines up the smoke tower and connected to the fourth floor standpipes. They extinguished the fire on the fourth and fifth floors and evacuated the occupants. Engine 2 pumped a total of four lines into the dry standpipe. Two of these lines were laid by Engine 3.

Engine 3

Engine 3 laid two lines from the dry standpipe connections to Engine 2. The crew then took lines and air paks to the fourth floor by way of the smoke tower and assisted other crews in fire-fighting and rescue on the fourth and fifth floors. Captain Schoup was informed by a bystander of a serious fire problem on the east side of the building. He investigated and had his crew lay two

additional lines to the east side of the building. These lines were used to attack the fire in the upper floors.

A woman that was hanging onto a drainpipe was rescued by using a 45-foot extension ladder. The crew of Engine 3 then assisted in the search and rescue operations from the seventh to 11th floors. Engine 3 pumped a total of two lines which were used at the rear of the building.

Ladder 1

When Ladder 1 arrived, people were hanging from windows, standing on ledges and balconies awaiting rescue. Captain Jones had Ladder 1 spotted north of the main entrance to the hotel on Stone Avenue and raised the aerial for rescue operations. Ladder 1 rescued all occupants that could be reached by the aerial from this position. A woman jumped from an upper floor and was killed while the aerial was being extended for rescue. Ladder 1 used their 45-foot extension, 35-foot extension, and a 14-foot roof ladder for rescue purposes. After all occupants that could be reached with the aerial were rescued, the ladder pipe was used to extinguish fires in the eighth and ninth floor windows on the Stone Avenue side of the building. Later the crew went inside the building and assisted in searching for victims, setting up lights, and supplying equipment.

Ladder 3

When Captain Sedlack arrived with Ladder 3, the truck was spotted on the Pennington side of the building and the aerial was raised for rescue operations. The crew helped seven occupants from the building down the aerial. A 45-foot extension ladder was raised to the fourth floor on the Stone Avenue side were a male occupant was rescued. A 14-foot roof ladder was placed at the top of the 45-foot extension ladder reaching the fifth floor where three more occupants were rescued. Two men were sent to the 11th floor by way of the smoke tower and they rescued a male occupant. The rooms on the 11th floor were checked and several unconscious occupants were taken to the smoke tower. The crew then connected hose to standpipes and knocked down spot fires on the seventh, eighth, ninth and tenth floors. All of these rooms were checked for occupants and ventilated.

Rescue 1

First aid equipment and resuscitators from Rescue 1 were used on firefighters and hotel occupants.

2ND ALARM

The second alarm was dispatched at 0026. The response consisted of Engines 5 and 7; Ladder 2; and Rescue 2.

Engine 5

Captain Jensen had the crew of Engine 5 take one section of 2-1/2 inch hose and two sections of 1-1/2 inch hose up the smoke tower to the upper floors. The crew assisted in firefighting and rescue operations on several of the upper floors.

Engine 7

Captain Regilio reported that on the arrival of Engine 7 there were numerous people at the windows from the fourth floor up. Smoke and flames were coming from several windows on the northeast end of the hotel. The crew of Engine 7 put up a 24-foot extension ladder to the roof of the building to the east of the hotel. From the roof

of this building, the crew put up a 24-foot extension and a 14-foot roof ladder reaching some windows on the northeast part of the hotel building. Some occupants used these ladders to escape. The body of a small boy was laying on the roof and apparently had jumped from an upper floor. The crew later assisted in extinguishing spot fires and searching for occupants throughout the hotel.

Ladder 2

When Captain Machado arrived with Ladder 2, he saw several people at windows yelling for help. He immediately had the aerial ladder put into operation for rescue. Two female occupants were rescued from a sixth floor window on the northwest corner of the building. Before these two women reached the ground, fire belched from this window. The ladder truck was then repositioned further south for more rescue. From this location three elderly people were brought down from the seventh floor. The aerial was then fully extended to a point where men on top of the ladder were able to reach up and rescue occupants off the ninth floor balcony. After rescue operations were completed from the outside the crew went inside to assist with search and rescue operations. A 45-foot extension ladder was taken from Ladder 2 for rescue operations. This ladder retracted while three firefighters were attempting a rescue. All three were seriously injured, one with a broken pelvis, one with a broken ankle, and the other with serious lacerations of the arm and leg. The cause of this accident is under investigation.

Rescue 2

First aid equipment and resuscitators from Rescue 2 were used on firefighters and hotel occupants.

3RD ALARM

The third alarm was dispatched at 0028. The response consisted of Engines 8 and 10; and Rescue 3 and 5.

Engine 10

Captain Branaman and his crew entered the building at the fourth floor level of the smoke tower where they extended hose lines and worked their way to the north fire escape. They then proceeded to the seventh floor and attacked some fire at that point. They then assisted in search and rescue from the seventh to llth floors.

Engine 8

When Engine 8 arrived at the scene Captain Porter had his crew advance 1-1/2 inch lines to the sixth floor where they assisted in firefighting operations. They later moved to the seventh floor to assist in firefighting. The crew assisted in first aid treatment and administered oxygen to personnel overcome by smoke. After the fire was knocked down, they assisted in the thorough search of the building for occupants.

Rescue 3 and 5

First aid equipment and resuscitators from Rescue 3 and 5 were used on firefighters and hotel occupants.

4TH ALARM

The fourth alarm was dispatched at 0045. The response consisted of Engines 4, 6, 9, and 11; Ladder company 4; and Rescue 4.

Engine 4

Upon arrival of Engine 4, Captain McCarty and his crew took two sections of 1-1/2 inch and two sections of 2-1/2 inch hose to the fifth floor. A line on the fifth floor was extended and a line moved to the sixth floor. The crew of Engine 4 entinguished fire on the sixth floor and moved upward a floor at a time, extinguishing fire as they progressed and searched for survivors. After reaching the top floor they participated in rechecking the north wing for survivors and extinguished spot fires as they progressed downward.

Engine 6

When Engine 6 arrived at the scene, Captain Facio took his crew to the sixth floor to assist in search and rescue operations.

After completing the sixth floor assignment, the crew assisted in rechecking throughout the building for occupants and extinguishing spot fires.

Engine 9 and Ladder 4

The aerial ladder truck normally used by the company of Ladder 4 was out of service for major overhaul at the time of this fire. A reserve engine had been placed in service for use by the ladder company. At the time of dispatch, two members of the ladder company were out on a rescue call and one man was assigned as driver for the District 2 Chief. Engine 9 responded with four men and ladder company 4 responded with two men and upon arrival at the scene operated as one company under the command of Captain Grimes.

This crew took two sections of 1-1/2 inch and two sections of 2-1/2 inch hose to the upper floors. Upon reaching an upper floor where there was fire, part of the crew assisted in firefighting and the others assisted in removing victims to the mezzanine where a first aid receiving station had been set up. The crew then assisted in a room to room search of the eighth, ninth, tenth and 11th floors.

Engine 11

Upon arrival of Engine 11, Captain Moran had his crew take one section of 2-1/2 inch hose and some other equipment to the ninth floor. The crew assisted in firefighting on the ninth floor and also established a supply depot for equipment being hoisted from the street. The crew rescued one male occupant from the ninth floor who appeared to be in good condition. They also assisted in removing other victims of the fire.

Rescue 4

The crew of Rescue 4 was on a rescue call at the time the companies from station 9 were dispatched. As soon as they cleared this call, they responded to the scene. At the scene the rescue crew assisted in providing first aid treatment for firefighters.

OFF DUTY PERSONNEL

Reserve Engine 2523

An off duty crew commanded by Captain Hopkins took Engine 2523 to the scene and assisted in firefighting operations from the seventh floor to the roof. They later participated in rechecking the building for survivors and extinguishing spot fires.

Reserve Engine 8027

An off duty crew commanded by Captain Mazon took Engine 8027 to the scene. This crew assisted in checking for victims on the eighth

and ninth floor.

In addition to these two off duty companies 82 other off duty personnel were sent to the scene during the emergency to assist in firefighting, search and rescue, recovery of equipment, etc.

Eight of the 11 off duty Training personnel reporting were new recruits who were taken to the scene to assist and were supervised by their Training Officers.





INCIDENT	T Report, continued:	Page No.:
Master I	Report No.: 459	Date: 12/31/70
CAUSE:	From:	
	To:	
0130 Ho	red at the Pioneer Internat ours on December 20, 1970 to be cause.	cional Hotel at approximately co begin investigation into
and the	re were two major fire ori sixty feet (60'). No nat	r Floor in the public hallway igin areas separated by approx-tural or accidental causes could
In my o intent.	pinion, this was a deliber Therefore, fire cause is	rate, man-made fire, with malicious arson.
	g.	L.D. Gilmore, Captain Tucson Fire Department Fire Prevention Division
LDG/sma	t	
		2.0
		and the state of the party of
	TUCSON FIRE	Signature
	. Ideson Fire	DEPARIMENT
	(FIRE CAUS	E REPORT)
INCIDEN:	T Report, continued:	Page No.:
laster I	Report No.: 459	Date:12/31/70_
CAUSE:		
	To:	
0300 I	ived at the Pionser Interna Jours on December 20, 1970 The cause.	ational Notel at approximately to begin investigation into
and th	ere were at least two majo	th Floor in the public hallway or fire origin areas separated). No natural or accidental

In my opinion, this was a deliberate, man-made fire, with malicious intent. Therefore, fire cause is arson.

R.B. Slagel, Chief Fire Prevention Division

RBS/smw

Signature Signature

Greater Tucson Fire Foundation

Thank you for taking an interest in Tucson Fire Department history —

This is one of many sections that contain information, documents, letters, newspaper articles, pictures, etc. They have been collected and arranged in chronological order or by a subject. These items were collected, organized and entered into a computerized database by Dave Ridings retired Assistant Chief Tucson Fire Department, Al Ring friend of the department, Greater Tucson Fire Foundation and with the help of many friends and fellow firefighters.

All graphics have been improved to make the resolution as good as possible, but the reader should remember that many came from copies of old newspaper articles. This also applies to other items such as documents, letters, etc.

Credit to the source of the documents, photos, etc. is provided whenever it was available. We realize that many items are not identified and regret that we weren't able to provide this information. As far as the newspaper articles that are not identified, 99% of them would have to be from one of three possible sources. The *Arizona Daily Star*, The *Tucson Citizen* and the *Tucson Daily Citizen*, for which we want to give a special thanks.

Please use this information as a reference tool only. If the reader uses any of the information for any purpose other than a reference tool, they should get permission from the source.

Should the reader have additional information on the above subject we would appreciate you sharing it with us. Please see the names and contact information on the 1st. TFD Archives page right below this paragraph.

